



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21009695/Uqf3e2	
			Date: 12/11/2021	
			Code: LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SLN 6256Z
	<b>Policy No.</b>	Z21VP05029146	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	21/21/21/VP05/024930	<b>Excess (\$)</b>	500.00
	<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	16/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HONDA JAZZ 1.5 (A)	<b>c.c</b>	1498
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
	<b>Chassis No.</b>	JHMGK5850HX201177	<b>Colour</b>	BLACK
	<b>Odometer</b>	63374 KM	<b>Steering</b>	AFFECTED
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	185/55 R16	DUNLOP	6 mm
	<b>L/H Front Tyre</b>	185/55 R16	DUNLOP	6 mm
	<b>R/H Rear Tyre</b>	185/55 R16	DUNLOP	6 mm
	<b>L/H Rear Tyre</b>	185/55 R16	DUNLOP	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, N/S REAR, FRONT PORTION AND ROOFTOP. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	05/09/2021	<b>Inspection Date</b>	16/09/2021
	<b>Survey held at</b>	VAC AUTO CENTRE PL NO.1 KAKI BUKIT AVE 6 #02-11 SNGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$56,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>25 Working Days</b>	