

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLN 62562

at Workshop m/s

VAC

of

Insured:

Policy No.

Claims No.

21/21/21/VP05/024930

Sum Insured:


Excess:

\$500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

\$561.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

25

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

7:40

Veh No:

SLN 62562

Yr Regn:

11/5/17

Type: ~~M. Car~~ / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make:

Honda Jazz 1.5 c.c 1498

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

63374

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMAK1810HX201177

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Inorder~~ / Jammed / Leaked / Burnt or ~~offered~~Brake: ~~Inorder~~ / Jammed / Leaked / Burnt orModi: Nil / ~~8 Run~~ / STD A/Rim or

Tyre Size:

F: 185 / 55 R16

R:

BS / ~~BUN~~ / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

5/9/21

D.O.I.

18/9/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / ~~Roof~~ or

N/S Rear 10/5 Body lift,

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA # 38860 50/5 yrs Smith. Dep 800

Not 4 817140

agreed from Repairer Victor can repair at 4/5 &amp; 17k.

5/11/21 confirmed 4/5 &amp; 16,500 w/h Victor (Red \$18727.45, 53%)

Date/Time, File Pass to?

☐

Preli. Report

1) 05/11 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

25

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

Report Format :

OD

Lump Sum ~~11.2k~~ (\$ 16500

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL



# VAC AUTO CENTRE PTE LTD

UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883  
Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

Not Authorized  
N/A

Excess \$500?

WATACROSS?

16/9/21  
1/5 \$16,500 25 days

4/5 16,500

Page 1

Regn No : SLN6256Z

Vehicle Make & Model : Honda Jazz 1.5 VTIR CVT

| ITEM NO            | DESCRIPTION OF ITEMS                                   | QUANTITY<br>(Piece/Set) | UNIT PRICE<br>(S\$) | AMOUNT<br>(S\$)   |
|--------------------|--------------------------------------------------------|-------------------------|---------------------|-------------------|
| <b>Cost Price:</b> |                                                        |                         |                     |                   |
| 1                  | Front bonnet <i>D/S</i>                                | 1                       | \$ 320.00           | \$ 320.00 ✓       |
| 2                  | Front bonnet insulator <i>NF</i>                       | 1                       | \$ 100.00           | \$ 100.00 X       |
| 3                  | Front bonnet insulator clips <i>NN</i>                 | 10                      | \$ 2.50             | \$ 25.00 X        |
| 4                  | Front bonnet rubbers <i>neu</i>                        | 2                       | \$ 28.00            | \$ 56.00 ✓        |
| 5                  | Front bonnet hinges LH/RH <i>but</i>                   | 2                       | \$ 30.00            | \$ 60.00 ✓        |
| 6                  | Front bonnet lock <i>ywl</i>                           | 1                       | \$ 75.00            | \$ 75.00 ✓        |
| 7                  | Front bonnet lock cable <i>11</i>                      | 1                       | \$ 90.00            | \$ 90.00 X        |
| 8                  | Front bonnet stand <i>11</i>                           | 1                       | \$ 60.00            | \$ 60.00 X        |
| 9                  | Front bonnet garnish LH <i>cut</i>                     | 1                       | \$ 30.00            | \$ 30.00 ✓        |
| 10                 | Front bonnet garnish RH <i>cut</i>                     | 1                       | \$ 50.00            | \$ 50.00 ✓        |
| 11                 | Front bumper <i>cut</i>                                | 1                       | \$ 420.00           | \$ 420.00 ✓       |
| 12                 | Front bumper lower grille <i>11</i>                    | 1                       | \$ 180.00           | \$ 180.00 X       |
| 13                 | Front bumper fog lamps LH/RH <i>11</i>                 | 2                       | \$ 185.00           | \$ 370.00 X       |
| 14                 | Front bumper fog lamp covers LH/RH <i>11</i>           | 2                       | \$ 25.00            | \$ 50.00 X        |
| 15                 | Front bumper LED lights LH/RH <i>11</i>                | 2                       | \$ 185.00           | \$ 370.00 X       |
| 16                 | Front bumper reinforcement <i>11</i>                   | 1                       | \$ 220.00           | \$ 220.00 X       |
| 17                 | Front bumper side retainers LH/RH <i>neu</i>           | 2                       | \$ 28.00            | \$ 56.00 ✓        |
| 18                 | Front bumper clips <i>neu</i>                          | 10                      | \$ 2.50             | \$ 25.00 ✓        |
| 19                 | Front fenders LH/RH <i>10/3 cut</i>                    | 2                       | \$ 180.00           | \$ 360.00 X       |
| 20                 | Front fender innershields LH/RH <i>11</i>              | 2                       | \$ 100.00           | \$ 200.00 X       |
| 21                 | Front fender innershield clips <i>11</i>               | 30                      | \$ 2.50             | \$ 75.00 X        |
| 22                 | Front grille with lower chrome/grille emblem <i>11</i> | 1                       | \$ 275.00           | \$ 275.00 X       |
| 23                 | Front grille top garnish <i>11</i>                     | 1                       | \$ 20.00            | \$ 20.00 X        |
| 24                 | Front grille clips <i>11</i>                           | 5                       | \$ 3.00             | \$ 15.00 X        |
| 25                 | Front headlamp assembly LH/RH <i>N/S one o/c RM 2X</i> | \$                      | 900.00              | \$ 1,800.00 1pc   |
| 26                 | Front headlamp lower brackets LH/RH <i>11</i>          | 2                       | \$ 30.00            | \$ 60.00 X        |
| 27                 | Front number plate garnish <i>11</i>                   | 1                       | \$ 60.00            | \$ 60.00 X        |
| 28                 | Front support panel <i>11</i>                          | 1                       | \$ 360.00           | \$ 360.00 X       |
| 29                 | Front support panel garnishes LH/RH <i>11</i>          | 2                       | \$ 45.00            | \$ 90.00 X        |
| 30                 | Front lower arm <i>11</i>                              | 2                       | \$ 145.00           | \$ 290.00 X       |
| 31                 | Front stabilizer link <i>11</i>                        | 2                       | \$ 45.00            | \$ 90.00 X        |
| 32                 | Front stabilizer bar <i>11</i>                         | 2                       | \$ 130.00           | \$ 260.00 X       |
| 33                 | Front wheel bearing <i>11</i>                          | 2                       | \$ 98.00            | \$ 196.00 X       |
| 34                 | Front wheel knuckle <i>11</i>                          | 2                       | \$ 120.00           | \$ 240.00 X       |
| 35                 | Front wheel knuckle cover <i>N/S</i>                   | 2                       | \$ 22.00            | \$ 44.00 X        |
| 36                 | Front shock absorber <i>11</i>                         | 2                       | \$ 240.00           | \$ 480.00 X       |
| 37                 | Front wheel suspension <i>11</i>                       | 2                       | \$ 110.00           | \$ 220.00 X       |
| 38                 | Front wheel drive shaft <i>11</i>                      | 2                       | \$ 720.00           | \$ 1,440.00 X     |
| 39                 | Front sub-frame lower/crossmember <i>11</i>            | 1                       | \$ 550.00           | \$ 550.00 X       |
| 40                 | Front sports rim <i>o/s cut/But</i>                    | 1                       | \$ 560.00           | \$ 560.00 1pc 250 |
| 41                 | Front door <i>10/3 cut</i>                             | 2                       | \$ 485.00           | \$ 970.00 ✓       |
| 42                 | Front door outer weatherstrip <i>neu</i>               | 2                       | \$ 50.00            | \$ 100.00 ✓       |
| 43                 | Front door black sticker <i>neu</i>                    | 2                       | \$ 38.00            | \$ 76.00 ✓        |
| 44                 | Front door visor <i>NZ</i>                             | 1                       | \$ 180.00           | \$ 180.00 X       |

3498

**VAC AUTO CENTRE PTE LTD** UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

Page 2

Regn No : SLN6256Z

Vehicle Make/Model : Honda Jazz 1.5 VTIR CVT

| ITEM NO | DESCRIPTION OF ITEMS | QUANTITY<br>(Piece/Set) | UNIT PRICE<br>(S\$) | AMOUNT<br>(S\$) |
|---------|----------------------|-------------------------|---------------------|-----------------|
|---------|----------------------|-------------------------|---------------------|-----------------|

**Cost Price:**

|    |                                                 |    |             |                          |
|----|-------------------------------------------------|----|-------------|--------------------------|
| 45 | Front side mirror RH <i>3/20</i>                | 1  | \$ 250.00   | \$ 250.00 ✓              |
| 46 | Front door glass RH <i>shotted</i>              | 1  | \$ 360.00   | \$ 360.00 ✓              |
| 47 | Front door inner weatherstrip <i>new</i>        | 2  | \$ 60.00    | \$ 120.00 ✓              |
| 48 | Front door quarter glass <i>shotted</i>         | 2  | \$ 240.00   | \$ 480.00 ✓              |
| 49 | Front windscreen glass <i>3/20</i>              | 1  | \$ 1,200.00 | \$ 1,200.00 ✓            |
| 50 | Front windscreen top moulding <i>new</i>        | 1  | \$ 50.00    | \$ 50.00 ✓               |
| 51 | Front windscreen side mouldings <i>new</i>      | 2  | \$ 80.00    | \$ 160.00 ✓              |
| 52 | Front roof panel <i>body</i>                    | 1  | \$ 630.00   | \$ 630.00 ✓              |
| 53 | Front roof outer lining <i>washed</i>           | 2  | \$ 155.00   | \$ 310.00 ✓              |
| 54 | Front roof inner rail panel - front <i>sent</i> | 1  | \$ 65.00    | \$ 65.00 ✓               |
| 55 | Front roof inner rail panel - centre <i>new</i> | 1  | \$ 110.00   | \$ 110.00 ✓              |
| 56 | Front roof inner rail panel - rear <i>new</i>   | 1  | \$ 125.00   | \$ 125.00 ✓              |
| 57 | Front roof inner lining trim <i>washed</i>      | 1  | \$ 535.00   | \$ 535.00 ✓              |
| 58 | Front roof pillar <i>new/sent</i>               | 2  | \$ 600.00   | \$ 1,200.00 ✓            |
| 59 | Front roof inner pillar garnish <i>new</i>      | 1  | \$ 55.00    | \$ 55.00 ✓               |
| 60 | Dashboard <i>cut</i>                            | 1  | \$ 760.00   | \$ 760.00 ✓              |
| 61 | Rear door <i>new/sent</i>                       | 2  | \$ 480.00   | \$ 960.00 ✓              |
| 62 | Rear door outer handle <i>o/s cut</i>           | 2  | \$ 80.00    | \$ 160.00 <i>ipc</i>     |
| 63 | Rear door outer sticker <i>new</i>              | 2  | \$ 20.00    | \$ 40.00 ✓               |
| 64 | Rear fender <i>new/sent</i>                     | 2  | \$ 460.00   | \$ 920.00 ✓              |
| 65 | Rear fender lamp <i>new</i>                     | 2  | \$ 290.00   | \$ 580.00 ✓              |
| 66 | Rear tailgate <i>new</i>                        | 1  | \$ 600.00   | \$ 600.00 ✓              |
| 67 | Rear bumper <i>new</i>                          | 1  | \$ 240.00   | \$ 240.00 ✓              |
| 68 | Rear bumper clips <i>new</i>                    | 10 | \$ 2.50     | \$ 25.00 ✓               |
| 69 | Rear bumper grille LH/RH <i>new</i>             | 2  | \$ 20.00    | \$ 40.00 ✓               |
| 70 | Rear side retainers LH/RH <i>sent/new</i>       | 2  | \$ 15.00    | \$ 30.00 ✓               |
| 71 | Rear sports rim <i>sent/washed 250x2=500</i>    | 1  | \$ 560.00   | \$ 560.00 <i>500 S.N</i> |
| 72 | Rear taillamp RH <i>one</i>                     | 1  | \$ 240.00   | \$ 240.00 ✓              |
| 73 | Rear axle beam assembly <i>sent/new</i>         | 1  | \$ 750.00   | \$ 750.00 ✓              |
| 74 | Rear axle beam bearings <i>boxed</i>            | 2  | \$ 150.00   | \$ 300.00 ✓              |
| 75 | Rear shock absorbers <i>new/sent o/s sent</i>   | 2  | \$ 180.00   | \$ 360.00 <i>7pc</i>     |

|            |  |  |           |              |
|------------|--|--|-----------|--------------|
|            |  |  | Sub-total | \$ 23,783.00 |
| Add        |  |  | 15%       | \$ 3,567.45  |
| Cost Price |  |  | Total     | \$ 27,350.45 |

**Special Nett Items:**

|   |                                                |   |           |                         |
|---|------------------------------------------------|---|-----------|-------------------------|
| 1 | Front windscreen sealant <i>new</i>            | 1 | \$ 42.50  | \$ 42.50 <i>40</i>      |
| 2 | Front RH door quarter glass sealant <i>new</i> | 1 | \$ 30.00  | \$ 30.00 ✓              |
| 3 | Front number plate with casing <i>new</i>      | 1 | \$ 45.00  | \$ 45.00 ✓              |
| 4 | Rear windscreen sealant <i>new</i>             | 1 | \$ 42.50  | \$ 42.50 <i>40</i>      |
| 5 | Rear wheel tyre RH <i>put</i>                  | 1 | \$ 125.00 | \$ 125.00 <i>75 60%</i> |
| 6 | ERP bracket <i>new</i>                         | 1 | \$ 12.00  | \$ 12.00 ✓              |

|              |  |  |       |           |
|--------------|--|--|-------|-----------|
| S/Nett Items |  |  | Total | \$ 297.00 |
|--------------|--|--|-------|-----------|

199



# VAC AUTO CENTRE PTE LTD

UEN: 200210945Z

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Tel: 8618 8008 | Fax: 6636 5355 | Email: vacauto@singnet.com.sg

Page 3

Regn No : SLN6256Z

Vehicle Make &amp; Model : Honda Jazz 1.5 VTIR CVT

**Labour Charge Items:**

|                      |                                                                                |              |                    |      |
|----------------------|--------------------------------------------------------------------------------|--------------|--------------------|------|
| 1                    | Towing charge                                                                  | \$           | 120.00             | ✓    |
| 2                    | To check and rectify electrical wiring systems                                 | \$           | 200.00             | 50   |
| 3                    | To remove and <sup>replace</sup> front windscreen glass                        | \$           | 150.00             | 120  |
| 4                    | To remove and <sup>replace</sup> front <sup>quarter</sup> glass                | \$           | 200.00             | 120  |
| 5                    | To remove and refit front dashboard                                            | \$           | 250.00             | ✓    |
| 6                    | To remove and replace interior upholstery, roof lining and other damaged items | \$           | 400.00             | 180  |
| 7                    | To remove and refit front and rear sub-frame assembly and undercarriage member | \$           | 500.00             | 250  |
| 8                    | To remove and refit front seat in order to conduct works                       | \$           | 1180.00            | X    |
| 9                    | To remove, refit aircon condenser and refill aircon gas                        | \$           | 1150.00            | X    |
| 10                   | To remove and refit front radiator and top up coolant                          | \$           | 1100.00            | X    |
| 11                   | To conduct computerised 4-wheel alignment                                      | \$           | 180.00             | 80   |
| 12                   | To diagnose, erase, reset and reprogramme fault memory code after repair       | \$           | 250.00             | X    |
| 13                   | To rust proof affected rear areas                                              | \$           | 200.00             | X    |
| 14                   | To putty, respray painting & etc                                               | \$           | 2,000.00           | 1800 |
| 15                   | Panel beating, cut, weld, remove and replacing above parts                     | \$           | 2,700.00           | 2600 |
| <b>Labour Charge</b> |                                                                                | <b>Total</b> | <b>\$ 7,580.00</b> |      |

**Overall Estimate Parts & Labour****Grand total \$ 35,227.45**

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 13343  
 152  
 P- 15344-45-  
 S.N- 947  
 L- 5570  
 21861.45  
 202  
 11489