

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0764/2021/ZK
DATE : 14-Sep-21
WIP : 44180

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

8 days exclude 1 Sunday

Johnny Boo 2 Nov 21

OWNER'S NAME : M/S ORIENTAL SHEET PILING PTE LTD
ADDRESS : 1 COMMONWEALTH LANE
#02-03
SINGAPORE 149544
TELEPHONE : HP +65 86836633
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070171472
VEHICLE NO : **SGZ 6633 P**
MODEL CODE : Q8 3.0 TFSI
MODEL YEAR : 22/11/2018
ENGINE NO : DCB 047111
CHASSIS NO : WAUZZZF16KD006122
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Sep-21
PLACE OF ACCIDENT : ONE COMMONWEALTH CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGZ 6633 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO RENEW RHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	300.00	
3	TO INSTALL SOLAR FILM FOR RHS SIDE 1/4 GLASS.	S/N \$	400.00	
4	TO CARRY OUT WATER SEPAGE TEST 1/4 GLASS	S/N \$	200.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,800.00	
6	TO REMOVE AND REINSTALL REAR SEAT , BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,800.00	
SUB LABOUR CHARGES		:	\$	4,860.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGZ 6633 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE	S/N \$	900.00	\$	760.00
8	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY	S/N \$	1,800.00		
9	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$	8,100.00	\$	1,800.00
10	TO RESPRAY RHS REAR FENDER,RHS REAR DOOR,RHS FRONT DOOR , TWO DOOR COVERS , TWO DOOR HANDLES , RHS SILL PANEL ,DRAIN CHANNEL , ROOF CHANNEL , DOOR ENTRABCE REAR END PANELLING,RHS REAR DOOR WHEEL ARCH AND BOTH REAR WHEEL ARCH TRIMS.	\$	8,900.00	\$	3,550.00
11	TO CARRY OUT ALUMINIUM PRIMER WORKS	S/N \$	900.00		
12	TO RENEW RHS REAR RIM WITH TYRE AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 25,932.00	\$	6,582.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 6633 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 4,907.00	\$ 3,925.60
2	HEXAGON	1	\$ 5.00	
3	OVAL HEAD SCREW	1	\$ 4.00	
4	REAR DOOR SEAL	1	\$ 172.00	\$ 137.20
5	BONDING AGENT	1	\$ 49.00	
6	CLEANING SOLUTION	1	\$ 68.00	
7	APPLICATOR	1	\$ 8.00	
8	FRONT DOOR ATTACHMENT PART	1	\$ 231.00	
9	FRONT DOOR CATCH - RH	1	\$ 128.00	
10	HEXAGON	2	\$ 5.00	
11	OVAL HEAD SCREW	1	\$ 4.00	
12	FRONT DOOR HANDLE - RH	1	\$ 365.00	\$ 292.00
13	FRONT DOOR HANDLE CAP - RH	1	\$ 40.00	
14	FRONT DOOR COVER - RH	1	\$ 507.00	\$ 407.20
15	REAR DOOR - RH	1	\$ 4,907.00	\$ 3,925.60
16	REAR DOOR SEAL - RH	1	\$ 172.00	\$ 137.20
17	BONDING AGENT	1	\$ 49.00	
18	CLEANING SOLUTION	1	\$ 68.00	
19	APPLICATOR	1	\$ 8.00	
20	FRONT DOOR ATTACHMENT PART	1	\$ 231.00	
SUB TOTAL SPARE PARTS			\$ 11,928.00	\$ 8,824.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 6633 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	8,824.80
21	REAR DOOR CATCH - RH	1	\$ 105.00		
22	HEXAGON	2	\$ 5.00		
23	OVAL HEAD SCREW	1	\$ 4.00		
24	REAR DOOR SEAL - RH INNER	1	\$ 589.00		
25	REAR DOOR SEAL - RH OUTER	1	\$ 253.00	\$	202.00
26	SILL PANEL SEAL - RH	1	\$ 253.00		
27	REAR DOOR SEAL BRACKET - RH	1	\$ 43.00		
28	REAR DOOR HANDLE - RH	1	\$ 365.00	\$	292.00
29	REAR DOOR HANDLE CAP - RH	1	\$ 40.00		
30	REAR DOOR COVER - RH	1	\$ 507.00	\$	405.60
31	REAR DOOR WHEEL COVER - RH	1	\$ 196.00	\$	156.80
32	REAR SIDE PANEL FRAME - RH OUTER	1	\$ 8,415.00		
33	REAR SIDE WINDOW - RH	1	\$ 946.00		
34	RIVET	2	\$ 3.00		
35	PRIMER	1	\$ 20.00		
36	REAR SILL TRIM STRIP - RH	1	\$ 621.00		
37	FRONT SILL TRIM STRIP - RH	1	\$ 787.00		
38	REAR WHEEL ARCH - LH / RH	2	\$ 754.00		
39	WHEEL HOUSING LINER - RH	1	TBC		
40	SPOILER	1	\$ 52.00	\$	41.44
TOTAL SPARE PARTS		:	\$ 13,958.00	\$	9,922.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 6633 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 9,922.64
41	REAR MOUTING BAR	1	\$ 129.00	
42	WINDOW REGULATOR WITHOUT MOTOR - RH	1	\$ 375.00	
43	WINDOW REGULATOR MOTOR - RH	1	\$ 313.00	
44	DOOR INNER PANEL COVER - RH	1	\$ 103.00	
45	STATIC MIXER	1	\$ 8.00	
46	EPOXY ADHESIVE	1	\$ 113.00	
47	ALUMINIUM POWDER	1	\$ 573.00	
48	HARDENER	1	\$ 210.00	
49	ALUMINIUM PRIMER	1	\$ 212.00	
50	CLEANING BLOCK	1	\$ 77.00	
51	1/4 GLASS SEALANT	1	\$ 100.00	
52	ARCRYLIC SEALANT	1	\$ 180.00	
53	CRAVITY WAX	1	\$ 140.00	
54	STONE CHIP	1	\$ 180.00	
55	REAR RIM - RH	1	TBC	REPAIRED
56	REAR TYRE - RH	1	TBC	
57	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 29,099.00	\$ 9,922.64
TOTAL LABOUR CHARGES		:	\$ 25,932.00	\$ 6,582.00
GRAND TOTAL		:	\$ 55,031.00	\$ 16,504.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-02/11/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT