

ASS. FRY:

REF: CS/CTI21009698/Dtc

## ASSIGNMENT

COE 2024 Jan

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / ~~TP~~ RES / TP RES / OD RES / EVA / INV / MV  
 To Insp Vehicle No: \_\_\_\_\_  
 at Work to m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy Et \_\_\_\_\_  
 Claims to \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Check record) \_\_\_\_\_  
 Make Clr: \_\_\_\_\_

Veh No: SLU 8494C Yr Regn: Feb / 2009  
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Impreza CC 1498Colour White A/C: Insured / Std / RI / NASp. Reading 155583 T/Radio: Insured / Std / RI / NAEng No: EL16D619600C/Nr: J.F.2GE3KS59-G 003734

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / STD / STD A/Rim orTyre Size: F: 195/65 R15R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUBARU

TOYO / YOKO or

Firenza

Front

Rear


R/Bel. S mmR/Bel. S mmL/Bel. S mmL/Bel. S mmD.O.A. 14/09/2021D.O.L. 17/09/2021Survey held at CS Ong AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

(Police Condition)



Remark: The veh had commenced its  
 repair at the time of inspection.

Bel. of Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: 6 days Res.: Yes or NoLima Sum 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time	Action / Instruction
	China Taping SKL 5748
	MV 18K Finalized LS 5,500/- with 6 days of repair.
	LTA 6.1K
	HL 11.9K RED:36882.4;87%

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 61) \_\_\_\_\_  
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

3 + RS: \$ \_\_\_\_\_

Photos

Remarks:



# C. S. ONG AUTO PTE LTD

10, ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT, SINGAPORE 568047

TEL: 6484 1933 | FAX: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKL574S [YOUR INSURED] & SLU8494C [OUR CLIENT]  
ON 14/09/2021.

## ESTIMATED REPAIR COSTS FOR SLU8494C

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET <i>new</i>	\$ 2,380.00	X
1PC	BONNET INSULATOR <i>HH</i>	\$ 310.00	X
1PC	BONNET SEAL <i>HH</i>	\$ 150.00	X
1PC	HEAD LAMP LH / RH @ \$2,541.00 EACH <i>1/5 broken H/S HH 874.30</i>	\$ 5,082.00	✓
1PC	HEAD LAMP LOWER BRACKET RH <i>broken 95.70</i>	\$ 198.00	✓
1PC	HEAD LAMP ECU RH <i>HH</i>	\$ 1,180.00	X
1PC	HEAD LAMP WIRE HARNESS <i>HH</i>	\$ 1,992.00	X
1PC	FRONT GRILLE <i>mostly crack 597.30</i>	\$ 682.00	✓
1PC	FRONT GRILLE BASE <i>HS</i>	\$ 701.00	X
1PC	FRONT GRILLE CHROME <i>HS</i>	\$ 591.00	X
1PC	FRONT BUMPER <i>distorted 1 crack 654.30</i>	\$ 1,401.00	✓
1PC	FRONT BUMPER FOG LAMP RH <i>wave 404.80</i>	\$ 410.00	✓
1PC	FRONT BUMPER FOG LAMP HOLDER RH <i>HH HS</i>	\$ 278.00	X
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS <i>HH</i>	\$ 1,930.00	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$195.00 EACH <i>0/5 distorted</i>	\$ 390.00	✓
1PC	FRONT BUMPER LOWER GRILLE <i>HH H/S HH</i>	\$ 421.00	X
1PC	FRONT BUMPER SPONGE <i>HF</i>	\$ 423.00	X
1PC	FRONT REINFORCEMENT BAR <i>Dented 388.10</i>	\$ 1,292.00	✓
1PC	FRONT SUPPORT PANEL <i>1st Dented 695.70</i>	\$ 2,680.00	✓
1PC	A/C CONDENSOR <i>HH</i>	\$ 1,689.00	X
1PC	A/C CONDENSOR HIGH PRESSURE PIPE <i>HH</i>	\$ 931.00	X
1PC	A/C CONDENSOR LOW PRESSURE PIPE <i>HH</i>	\$ 401.00	X
1PC	RADIATOR ASSY <i>HH</i>	\$ 2,194.00	X
1PC	RADIATOR FAN MOTOR <i>HH</i>	\$ 452.00	X
1PC	RADIATOR FAN BLADE <i>HH</i>	\$ 201.00	X
1PC	RADIATOR FAN COWLING <i>HH</i>	\$ 499.00	X
1PC	FRONT FENDER RH <i>Dented 570.50</i>	\$ 1,429.00	✓
1PC	FRONT FENDER INNER SHIELD RH <i>trim 110.30</i>	\$ 251.00	✓
1PC	FRONT FENDER LAMP RH <i>HH</i>	\$ 295.00	X
1PC	FRONT WHEEL BEARING RH <i>2 Dam 280.40</i>	\$ 210.00	✓



1PC	FRONT WHEEL BEARING HUB RH HH		\$ 281.00	X
1PC	FRONT KNUCKLE ARM RH <del>2</del> <i>disturb</i>	321.10	\$ <del>895.00</del>	<del>2</del> ✓
1PC	FRONT LOWER ARM RH <del>2</del> <i>disturb</i>	333.10	\$ <del>590.00</del>	<del>2</del> ✓
1PC	FRONT ABSORBER RH <del>2</del> <i>disturb</i>	302.10	\$ <del>711.00</del>	<del>2</del> ✓
1PC	FRONT STABILIZER LINK RH HH		\$ 159.00	X
1PC	FRONT STABILIZER BAR HH		\$ 310.00	X
1PC	FRONT TIE ROD RH HH		\$ 210.00	X
1PC	FRONT TIE ROD END RH HH		\$ 241.00	X
1PC	STEERING RACK & PINION ASSY HH		\$ 2,890.00	X
1PC	DRIVE SHAFT RH HH		\$ 2,195.00	X
1PC	FRONT DOOR RH HH		\$ 1,874.00	X
1PC	FRONT DOOR WINDOW MOULDING RH HH		\$ 210.00	X
1PC	FRONT DOOR BLACK PLASTIC RH HH		\$ 94.00	X

5665.70

4532.56

PARTS SUM: \$ 41,703.00  
 PARTS LESS 20%: \$ 8,340.60  
 PARTS TOTAL: \$ 33,362.40

#### LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INSULATOR CLIPS HH		\$ 50.00	X
*	TO SUPPLY FRONT GRILLE CLIPS H/c		\$ 50.00	15/-
*	TO SUPPLY HEAD LAMP CLIPS HH		\$ 50.00	X
*	TO SUPPLY FRONT BUMPER CLIPS H/c		\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS HH		\$ 50.00	X
*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS H/c		\$ 50.00	15/-
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS HH		\$ 50.00	X
*	TO SUPPLY COOLANT HH		\$ 100.00	X
*	TO SUPPLY 1 PC SPORT RIM C/w	550.00	\$ 1,400.00	500/-
*	TO SUPPLY 1 PC TYRE HH		\$ 400.00	X
*	TO SUPPLY FRONT NO. PLATE & GARNISH HH		\$ 100.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,400.00	700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$ 2,400.00	800/-
*	TO TUFF COAT DAMAGED AREAS		\$ 200.00	40/-
*	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS		\$ 200.00	HH
*	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS		\$ 200.00	HH
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS		\$ 400.00	150/-
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT		\$ 120.00	60/-
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS		\$ 250.00	HH

- \* TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS 1780.00 \$ 200.00 30/-
- \* TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET \$ 300.00 44  
ALL MEMORIES TO FACTORY DEFAULT SETTINGS

LABOUR & S/N TOTAL: \$ 9,020.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 42,382.40

17/09/22 @ 1000hr

Met Arthur

4/5 hrs 6 days.

Ryan

LKK Auto



Check part prices.

68,62.56

4/5 5500/-

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	15/09/2021 14:43 (SGT)
Date of Accident	14/09/2021 16:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	MOULMEIN RD IN FRONT TUBERCULOSIS CONTROL UNIT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU8494C
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MOHAMED FADZLEEN BIN ZAINAL
NRIC No	SXXXX307G
Email Address	eremenko_elena@yahoo.com.sg
Mobile Phone No	(Phone) +65-93228632
Alternative Phone No	+65-93228632

#### VEHICLE PARTICULARS

Manufacturer	Subaru
Model	Impreza
Variant	IMPREZA 4DR 1.5R AWD 4AT ABS AIRBAG
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1498

#### INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

#### DRIVER

Name of Driver	EREMENKO ELENA
NRIC No	SXXXX959E

Date Of Birth	20/01/1986
Occupation	Indoor
Date Of Driving Pass	09/07/2013
Driving experience	8 YEARS AND 2 MONTHS
Gender	Female
Mobile Number	(Phone) +65-83838532
Alt. Phone Number	-
Email Address	eremenko_elena@yahoo.com.sg
Address	86 WILKIE ROAD #04-07 SPORE 228096
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	GIRLFRIEND
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tanglin Division Headquarters
Police Station Phone No	(Phone) +65-18003910000
Alt. Police Station Phone No	(Fax) +65-63964900
Police Station Address	21 Kampong Java Road Singapore 228892
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL574S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

## Describe Circumstances of the Accident

Refer to Police Report No: E/2020914/7036

### Declaration

We declare the foregoing particulars are true in every respect.

ch

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre  
Personnel





**SINGAPORE  
POLICE FORCE**



E/20210914/7036

1 of 2

**POLICE REPORT (NP299)**

Report No. E/20210914/7036

Police Station Of Origin  
Tanglin Division HQ  
21 Kampong Java Road SINGAPORE  
228892  
Tel No:1800-3910000

Date/Time Report Made 14/09/2021 20:26	Vide Report No.	Station Diary No.
Name Of Informant EREMENKO ELENA	Address 86 WILKIE ROAD #04-07 SINGAPORE 228096	
ID Type / ID No. NRIC NO / S8677959E	Contact No. Home/Office:	Mobile: 83838532
Nationality UZBEKISTAN	Email Address EREMENKO ELENA@YAHOO.COM.SG	
Occupation Self employed	Sex Female	Age 35
Institution/School Name	Date of Birth 20/01/1986	Race Caucasian
Date/Time Of Incident 14/09/2021 16:50	Location Of Incident MOULMEIN ROAD	

**Brief details.**

On the stated date and time, I was driving my vehicle SLU8494C along Moulmein road towards Balestier Road direction.

I was travelling straight along the extreme left lane when suddenly, a huge impact hit my vehicle on my front right portion.

The impact was huge and I knocked my right elbow against my driver's door as a result of being flung sideways.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 14/09/2021 20:26
Officer In-Charge Of Case:	Classification Of Case:





**SINGAPORE  
POLICE FORCE**



E/20210914/7036

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20210914/7036

My vehicle was also pushed to the left and collided with the kerb on my left.

I alighted to realise that SKL574S, which was initially on the lane on my right side by side with my vehicle, had swerved into my vehicle's path as the driver wanted to enter the Tuberculosis Centre on my left. I was caught completely off guard by the sudden manoeuvre of SKL574S and couldn't have avoided the accident.

Shortly after the accident, I started feeling pain over multiple areas of my body, including my neck, right shoulder, right wrist, chest and lower back areas as well.

I went to a clinic nearby the accident at Unihealth 24-Hr Clinic Toa Payoh for treatment and was given 5 days MC.

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:  
The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
14/09/2021 20:26

Classification Of Case:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	307G

### Vehicle Details

Vehicle No.:	SLU8494C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Sep 2021
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 4DR 1.5R AWD 4AT ABS AIRBAG
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	EL15D619600
Chassis No.:	JF1GE3KS59G003734
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,863.00
Original Registration Date:	13 Feb 2009
First Registration Date:	13 Feb 2009
Transfer Count:	3
Actual ARF Paid:	\$13,863.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	31 Jan 2024
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$6,196.00
<b>Total Rebate Amount:</b>	<b>\$6,196.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Sep 2021

OK



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 307G

### Vehicle Details

Vehicle No.: SLU8494C  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 14 Sep 2021  
Vehicle Make: SUBARU  
Vehicle Model: IMPREZA 4DR 1.5R AWD 4AT ABS AIRBAG  
Primary Colour: White  
Manufacturing Year: 2008  
Engine No.: EL15D619600  
Chassis No.: JF1GE3KS59G003734  
Maximum Power Output: 79.0 kW (105 bhp)  
Open Market Value: \$13,863.00  
Original Registration Date: 13 Feb 2009  
First Registration Date: 13 Feb 2009  
Transfer Count: 3  
Actual ARF Paid: \$13,863.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Jan 2024  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$13,024.00  
COE Rebate Amount: \$6,196.00  
**Total Rebate Amount: \$6,196.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Sep 2021

OK