

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/09/2021
Vehicle Reg. No.:	SHA9380T	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	21/08/2018
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEJU080153	Chassis No:	KMHC851CVKU107280
Odometer:	277614 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,737.20
Miscellaneous Items	11.00
Labour	760.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,508.20
+ GST 7.00% (S\$)	175.57
Nett Amount (S\$)	2,683.77

This claim is handled by: JUMANI BIN MASUDIN

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Sep 2021)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA9380T/16/09/2021 08:44
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	*459.40 FL XR
2	1		*REAR BUMPER CLIPS	20.00	0.00	NEC *22.00 FL CRK
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	*451.25 FL CRK
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FL ?XSVL
5	1		*REAR BUMPER TOWING COVER	20.00	0.00	*98.80 FL XSVL
6	1		*REAR BUMPER FOG LAMP	20.00	0.00	*201.50 FL XSVL
7	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*180.00 F XSVL
8	1		*REAR FENDER ADVERTISEMENT LOGO LH	0.00	0.00	*100.00 F NEC
9	1		*REAR FENDER ADVERTISEMENT LOGO RH	0.00	0.00	*100.00 F NEC
10	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	*55.00 F CRK

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	2,062.75
- List Item Discount on L Items (\$\$)	325.55
Total Parts (\$\$)	1,737.20

ComfortDelGro Engineering Pte Ltd/SHA9380T/16/09/2021 08:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400.00 ³⁵⁰
2	SPRAY PAINTING CHARGE	New	300.00 ²⁵⁰
3	REMOVE/REFIX REVERSE SENSOR	New	60.00 ³⁰
Gross Labour Cost (S\$)			760.00

ComfortDelGro Engineering Pte Ltd/SHA9380T/16/09/2021 08:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NR2 LKIC
16/9/2021 1540
LIS
2 DAYS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: