

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 22 Sep 2021

Preliminary Advice

Insured Vehicle No	: SJL7684Z	Accident Date	: 14/09/2021
TP Vehicle No	: SLM3721Y	Assignment Date	: 15/09/2021
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5
Date of Inspection	: 21/09/2021		
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,459.78
Revised Amount	:S\$	5,126.75
Check Items (Estimated)	:S\$	509.25
Total	:S\$	5,636.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to consistency checks, part prices and labour cost.