

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Nov 2021)
 Parts: 143 TOYOTA COROLLA 1.5 AXIO (M) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SCY8898G/12/11/2021 11:44
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*210.00 F ✓
2	1		*1 PC REAR BOOT	0.00	0.00	*290.00 F ✓
3	1		*1 PC REAR BOOT INNER LOCK	0.00	0.00	*60.00 F X
4	1		*1 PC REAR BOOT INNER RUBBER	0.00	0.00	*80.00 F ✓
5	1		*1 PC REAR BOOT LOGO	0.00	0.00	*30.00 F ✓
6	1		*1 PC REAR BOOT EMBLEM - COROLLA	0.00	0.00	*25.00 F ✓
7	1		*1 PC REAR BOOT EMBLEM - AXIO	0.00	0.00	*25.00 F ✓
8	1		*1 PC REAR BOOT EMBLEM	0.00	0.00	*25.00 F ✓
9	1		*1 PC REAR END PANEL	0.00	0.00	*230.00 F X
Total Parts (\$\$)						975.00

Cheng Hoe Motor Pte Ltd/SCY8898G/12/11/2021 11:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 SET REVERSE SENSOR	200.00 ✓
Sub Total (\$\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR BUMPER ASSY, TAIL LAMPS, REAR BOOT & ATTACHMENT, KNOCK & REPAIR REAR PANEL AND REALIGN THE SAME	New	550.00 450
2	PUTTY & RESPRAY ON REAR BOOT, REAR PANEL, REAR BUMPER	New	680.00 600
Gross Labour Cost (\$\$)			1,230.00

Cheng Hoe Motor Pte Ltd/SCY8898G/12/11/2021 11:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

parts - 121
 less 20% 24.2
 add SN 484
 add lab 1050
 121
 484
 40
 1050
 1695

L/S = \$11