



GOLD PERFORMANCE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259

Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN & GST Registration no:202039762K

15.09.2021

QUOTATION-THIRD PARTY CLAIM

Q:20210902

Pre-Repair Inspection / Assessment

Attention: The Claims Manager
cc: Vehicle Owner - Mr Tay Choon Mong

Email:claimsdept@sg.cntaiping.com

Dear Sir / Mdm

**ESTIMATE REPAIR COST OF SMW1572J (TOYOTA VELLFIRE) on an accident on 13.09.2021
at about 6pm along BuangKok Green towards SengKang**

Item	Description	Qty	Unit Price:S\$	Total:S\$
	<u>To supply parts:-</u>			
01	Rear Tailgate / Boots	1 pc	1,260.00	1,260.00
02	Pulling Cap	1 pc	42.00	42.00
03	Rear Tailgate Chrome Panel	1 pc	580.00	580.00
04	Rear "Vellfire" Badge	1 set	75.00	75.00
05	Rear Tailgate Inner Garnish (Cover)	1 pc	620.00	620.00
06	Rear Tailgate Rubber Moulding	1 pc	180.00	180.00
07	Rear WindScreen Assy	1 pc	770.00	770.00
08	Rear WindScreen Gum / Sealant	1 set	44.00	44.00
09	Taillamp Assy	2 pcs	680.00	1,360.00
10	Rear Tailgate Absorber Stand	2 pcs	190.00	380.00
11	Rear Bumper	1 pc	1,224.00	1,224.00
12	Rear Bumper Support Bracket	2 pcs	65.00	130.00
13	Rear Bumper Towing Hook Cover	2 pcs	22.00	44.00
14	Rear Tailgate Lock	1 pc	330.00	330.00
15	Rear Bumper Reverse Sensor	4 pcs	190.00	760.00
16	Rear Bumper Retainer Bracket	2 pcs	85.00	170.00
17	Rear Bumper Clips	10 pcs	2.50	25.00
18	Rubber Stopper for Tailgate	2 pcs	9.00	18.00
19	Rear Panel Garnish	1 pc	155.00	155.00
20	Spare Tyre Compartment (FloorBoard)	1 pc	380.00	380.00
21	Rear Taillamp Panel (Corner)	2 pcs	230.00	460.00
				9,007.00
	<u>To supply labour:-</u>			
01	To knock, weld, repair and renew all areas affected by the accident			1,600.00
02	To spray paint all areas affected by the accident			1,800.00



GOLD PERFORMANCE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259

Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN & GST Registration no:202039762K

15.09.2021

QUOTATION-THIRD PARTY CLAIM

Q:20210902

Pre-Repair Inspection / Assessment

Attention: The Claims Manager
cc: Vehicle Owner - Mr Tay Choon Mong

Email:claimsdept@sg.cntaiping.com

Dear Sir / Mdm

**ESTIMATE REPAIR COST OF SMW1572J (TOYOTA VELLFIRE) on an accident on 13.09.2021
at about 6pm along BuangKok Green towards SengKang**

Item	Description	Qty	Unit Price:S\$	Total:S\$
03	To remove and install rear windscreen			150.00
04	Loss of use - car rental for 12 days @ \$180.00	12 days	180.00	2,160.00
				14,717.00

We hope that our quotation will meet with your kind approval.

Thank you.

.....
Steven Ko
97289234