

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009711/AVCN2**Date:** 21/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00081032102

Claimant Vehicle No : SFG989P **Insured Vehicle No :** GBD9610K

Date of Loss: 08/09/2021 Nature of Claim: TP Claim No: SNM21D205236/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFG989P**

Make & Model: BMW 520I, 2.0 (A) Engine No: B1300303N20B20B

Reg. Date: 29/10/2012 (Man. Year: 2012) Chassis No: WBAXG12050DX51128

Colour: Blue Odometer: 203119 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 245/45R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,902.00	2,125.50	4,776.50	69.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	850.00	540.00	38.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,292.00	2,975.50	5,316.50	64.12
Approved Total (Overridden) (\$\$)		2,350.00		
Nett Amount (\$\$)	8,292.00	2,350.00	5,942.00	71.66

INSPECTION

Date of Assignment: 22/09/2021

Date Inspected: 21/09/2021 Inspected At: Tk Motor Workshop (HQ)
Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2022)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG989P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR L/H FENDER	Repair	1,850.00 F	*- FL
2	1		*REAR L/H LOWER ARM	Not Necessary	497.00 F	*- FL
3	1		*REAR L/H KNUCKLE ARM	Not Necessary	699.00 F	*- FL
4	1		*REAR L/H KNUCKLE HUP & BEARING	Not Necessary	527.00 F	*- FL
5	1		*REAR L/H SHOCK ABSORBER	Not Necessary	620.00 F	*- FL
6	1		*REAR BUMPER	Torn	1,627.00 F	*1,563.00 FL
7	1		*REAR BUMPER L/H SIDE RETAINER	Cracked	96.00 F	*96.00 FL
8	8		*REAR BUMPER CLIPS	Necessary	36.00 F	*36.00 FL
9	1		*REAR SPORT RIM L/H	Cut	950.00 FS	*600.00 FS
					Sub Total (\$\$)	6,902.00 2,295.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 169.50
					Total Parts (\$\$)	6,902.00 2,125.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	COMPUTER WHEEL ALIGHTMENT	New	90.00	80.00
2	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	280.00	0.00
3	WIRING	New	50.00	30.00
4	TO REMOVE & REFIX REAR INTERIOR UPHOSLY	New	80.00	0.00
5	TO SPRAY PAINTING	New	450.00	400.00
6	TO APPLY UNDERCOATING ON THE REPAIRED PANEL	New	60.00	40.00
7	LABOUR CHARGE FOR PANEL BEATING & WELDING,REMOVING ALL DAMAGE PARTS AND REPLACING OF THE NEW PARTS ETC	New	380.00	300.00
Gross Labour Cost (\$)			1,390.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >