

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0233/2021
DATE : 10-SEP-2021

DS => Steve (LKK-Auto)

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

ZHR

OWNER'S NAME : WASTE MANAGEMENT PTE LTD
ADDRESS : 911 BUKIT TIMAH ROAD
S(589622)
TELEPHONE NO : 64686559/96263079

Recommend Repair 5 Days

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-YP769K
VEHICLE NO : GBD9137K
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25361168A
CHASSIS NO : JN1MC2E26Z0003984
MILEAGE : 1 KM
DATE IN : 10/09/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 06/09/2021

Lat

\$80 x 5

\$400.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBD9137K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	240.00
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120.00
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
5	ZZ/001	REMOVE/INSTALL BLOWER/HEATER UNIT TO FACILITATES REPAIRS & REFILL AIRCOND GAS	360.00	.00
6	ZZ/002	REMOVE/INSTALL DASHBOARD	240.00	240.00
7	ZZ/003	REPAIR LH FR PANEL CORNER & FR PANEL RENEW FR CENTER PANEL	1560.00	1365.00
8	ZZ/004	S/PAINT FR CENTER/FR PANEL & LH FR CORNER PANEL	1000.00	500.00
TOTAL LABOUR CHARGES			3788.00	2613.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD9137K

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 SUNDRIES	NPN			20.00	OK
2 EMBLEM-RADIATOR	62889-1JA0A	79.90			X
3 CLIP(1.3X10)	01553-05323	13.00			OK
4 LAMP ASSY-RH	26010-3XA0D	441.40			OK
5 PANEL-FRONT	F1202-3XAMA	1227.50			OK
6 GRILLE-RADIATOR	62310-3XA0C	527.30			X
SUB TOTAL		1681.90	0.00	20.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		336.38	0.00	0.00	
GRAND TOTAL		1345.52	0.00	20.00	
OVERALL TOTAL		1365.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBD9137K

NETT ITEM	1681.90
LESS 20.00%)	-336.38
NETT AMOUNT	1345.52
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	2613.00
TOTAL SPARE PARTS CHARGES	1365.52
TOTAL CHARGES	3978.52
ADD 7 % GST	278.50
GRAND TOTAL	4257.02