

ASS. BY:

REF: CS/SMR 21009716/Dgg 3

ASSIGNMENT

CDE Oct 2027

From: _____ Date: _____

Estimate Cost: _____

OD / P / RES / DD RES / EVA / RV / MV

To Inspect Vehicle No: _____

at V/O of _____

by _____

Insurance _____

Policy No _____

Claimed to TAX/09/21/2037

Sum Insured _____

Excess _____

(Check records)

Make Model _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. of Market Value: _____

IDAC Ancillary Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repair: 6 days Res.: Yes or No

Lump Sum 71P % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 2577 D Yr Reg: Oct / 2019

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq CC 1580

Colour: Blue A/C: Insured / Std / Ref / NA

Sp. Reading 249236 T/Radio: Insured / Std / Ref / NA

Eng/No: G4LEKU400828

C/Nr: KMHC851CVLU187598

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: RE / S/R / STD A/R or

Tyre Size: F: 195/65 R15 R: 11

ES / DUN / EXNOVA / GY / FS / LZA / MIC / DHTSU / PIR / SURE /

TOYO / YOKO or

Washlake

Front R/Bal S min L/Bal S min

D.O.A. 16/09/22 D.O.I. 17/09/22

Survey held at 21st St Sui Ming

Des. of Damages: F/R / Rear / O/S / N/S / W/C / Roof/Top or

6/5 Rnt

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMR SHB 463S

04/05/22 Inspr 91P 9,969.04 with 6 days of rep.
(Ref # 10491.12, 51%)

Date/Time, File Pass to?

11/5 final

Date/Time, File Return to?

2

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ off inspection (\$

Survey Fee:

Transportation

8 + 8 =

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 16-Sep-21

INSURANCE: SMART

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 2577D

Description	Qty	List Price	Amount
Front Bumper Cover <i>distorted</i>	1	\$ 418.30	\$ 418.30
Front bumper top cover <i>HL</i>	1	\$ 476.30	\$ 476.30
Front Bumper Bracket Top (RH) <i>HL</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (RH) <i>HL</i>	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (RH) <i>HL</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>HL</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (RH) <i>cat SVL</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (RH) <i>HL</i>	1	\$ 153.80	\$ 153.80
Day Light , RH <i>HL</i>	1	\$ 642.50	\$ 642.50
Headlamp Support Panel Assy <i>minny wheel</i>	1	\$ 949.30	\$ 949.30
Headlamp(RH) <i>Scratched</i>	1	\$ 3,987.30	\$ 3,987.30
Front Fender(RH) <i>Distorted fender</i>	1	\$ 490.70	\$ 490.70
Front Fender Shield (RH) <i>HL torn</i>	1	\$ 164.70	\$ 164.70
Frt Door(RH) <i>HL Distorted</i>	1	\$ 1,797.20	\$ 1,797.20
Front Door Protector(RH) <i>HL</i>	1	\$ 186.20	\$ 186.20
Rocker Panel Outer Garnish <i>HL</i>	1	\$ 715.60	\$ 715.60
Front Wheel Rim (RH) <i>2 distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub Cap and hub assy (RH) <i>Down</i>	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap <i>cat</i>	1	\$ 346.40	\$ 346.40
Front Shock Absorber(Assy)(RH) <i>2 Vst</i>	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (RH) <i>HL</i>	1	\$ 372.50	\$ 372.50
Front Drive Shaft (RH) <i>HL</i>	1	\$ 1,136.70	\$ 1,136.70
Front drive shaft extension RH <i>HL</i>	1	\$ 1,125.80	\$ 1,125.80
Rack & Pinion Assy <i>Down 1 St</i>	1	\$ 1,087.40	\$ 1,087.40
STG Tie Rod <i>HL</i>	1	\$ 125.60	\$ 125.60
STG Tie End <i>Down</i>	1	\$ 94.70	\$ 94.70
Stabilizer Bar <i>HL</i>	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link <i>HL</i>	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (RH) <i>2 distorted</i>	1	\$ 596.80	\$ 596.80
Knuckle Arm (RH) <i>2 distorted</i>	1	\$ 663.60	\$ 663.60
SUB TOTAL			\$ 18,465.70
LESS 20%			\$ 3,693.14
DISCOUNTED TOTAL			\$ 14,772.56
Front Fender Advertisement Logo (RH) <i>HL</i> SN	1	\$ 100.00	\$ 100.00
Emblem-Blue Drive (RH) <i>HL</i> List SN	1	\$ 26.60	\$ 26.60
Front Door Comfort Logo (RH) <i>HL</i> SN	1	\$ 75.00	\$ 75.00
Front Door Advertisement Logo (RH) <i>HL</i> SN	1	\$ 100.00	\$ 100.00
Rocker Panel Outer Advertisement <i>HL</i> SN	1	\$ 120.00	\$ 120.00
Front Tyre(RH) <i>HL</i> SN	1	\$ 216.00	\$ 216.00
SUB TOTAL			\$ 637.60

Labour Charge			
Panel Beating	1	\$1,600.00	\$1,600.00
Spray Painting Charge	1	\$1,400.00	\$1,400.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00
Re-set Frt Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00
Re-set Frt ABS System	1	\$200.00	\$200.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,050.00
ESTIMATE TOTAL			\$ 20,460.16
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance			

600/-
600/-
30/-
40/-
44
44 60/-
44
60/-
150/-
44
44 1690.00
44
150/-

17/09/2021 @ 0945h

Not Antenna

4 P/Put

Photo after repair
with damaged parts

1 Man

2 Kk Auto

6 days

8

7/P 9969.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer: LIM TAN
 Company: 01-42
 License NO: SHC 2577D
 Odometer:

Date: 9/17/2021 11:25 AM
 VIN
 Technician:
 Order NO:

VEHICLE ALIGNMENT REPORT

HYUNDAI i30 (GD) All Models, 13-13 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°39'	3°44'	4°44'	5°00'
		Right	5°25'	3°44'	4°44'	5°46'
	Camber	Left	-0°42'	-1°00'	0°00'	-0°30'
		Right	-3°18'	-1°00'	0°00'	-3°24'
	Toe	Left	0°03'	-0°06'	0°06'	-1°21'
		Right	0°12'	-0°06'	0°06'	1°39'
Total		0°15'	-0°12'	0°12'	0°18'	
Rear	Camber	Left	-1°42'	-1°30'	-0°30'	-1°36'
		Right	-2°06'	-1°30'	-0°30'	-2°00'
	Toe	Left	0°06'	0°03'	0°30'	0°06'
		Right	0°00'	0°03'	0°30'	0°00'
		Total	0°06'	0°06'	1°00'	0°06'
	Thrust Angle		0°03'	99°59'		0°03'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	14°08'	13°18'	14°18'	14°08'
		Right	14°30'	13°18'	14°18'	14°30'
Included Angle		Left	13°26'	99°59'	99°59'	13°38'
		Right	11°12'	99°59'	99°59'	11°06'
Toe Out On Turns		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Max Turn Inside		Left	----	99°59'	99°59'	----
		Right	----	99°59'	99°59'	----
Toe Curve Change		Left	----	0°00'	199°59'	----
		Right	----	0°00'	199°59'	----
Setback		Front	2mm	2540mm	2540mm	2mm
		Rear	0mm	2540mm	2540mm	0mm
Track Width Diff.			-17mm			-17mm
Wheel Base Diff.			2mm			2mm
Front Ride Height		Left	----	2540mm	2540mm	----
		Right	----	2540mm	2540mm	----
Rear Ride Height		Left	----	2540mm	2540mm	----
		Right	----	2540mm	2540mm	----
Frame Angle						----

ONE STOP AUTOMOTIVE SOLUTION

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC2577D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Sep 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU400828
Chassis No.:	KMHC851CVLU187598
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,485.00
Original Registration Date:	30 Oct 2019
First Registration Date:	30 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$12,679.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2027
PARF Rebate Amount:	\$9,509.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,460.00
COE Rebate Amount:	\$18,706.00
Total Rebate Amount:	\$28,215.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Sep 2021

OK