

Lila Coelli

Not Authorized
16/9/21

2/5 \$1400
3 days

SGV9079R Nissan Latio

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>2 1/2</i>	\$ 556.90 ✓
2	1	Rear bootlid assy <i>1 1</i>	\$ 922.60 X
3	1	Rear end lower panel assy <i>2</i>	\$ 486.60 X
4	1	Rear left fender <i>1 1</i>	\$ 768.30 X
5	1	Rear right fender <i>1 1</i>	\$ 768.30 X
6	1	Rear spare tyre floor panel <i>1 ^</i>	\$ 948.40 X
			\$ 4,451.10
Less 30%			\$ 1,335.33
			\$ 3,115.77
7	2	Rear bumper side retainer <i>1 1</i>	\$ 86.40 X
8	2	Rear bumper bracket <i>1 1</i>	\$ 84.30 X
9	1	Rear bumper inner sponge <i>1 1</i>	\$ 128.60 X
10	1	Rear bootlid lock <i>1 1</i>	\$ 106.90 X
11	1	Rear bootlid lock catch <i>1 1</i>	\$ 62.60 X
12	1	Rear bootlid switch <i>1 1</i>	\$ 176.80 X
13	1	Rear bootlid weatherstrip <i>1 1</i>	\$ 188.70 X
14	1	Rear bootlid centre logo <i>1 1</i>	\$ 48.20 X
15	1	Rear bootlid 'latio' emblem <i>1 1</i>	\$ 46.30 X
16	1	Rear bootlid outer chrome moulding <i>1 1</i>	\$ 117.60 X
17	2	Rear bootlid hinges <i>1 1</i>	\$ 86.30 X
18	2	Rear bootlid no plate lamp <i>1 1</i>	\$ 103.10 X
19	2	Rear bootlid rubber stopper <i>1 1</i>	\$ 36.80 X
20	1	Rear bootlid inner trim board <i>1 1</i>	\$ 278.80 X
21	1	Rear left taillamp <i>1 1</i>	\$ 476.40 X
22	1	Rear right taillamp <i>1 1</i>	\$ 476.40 X
23	1	Rear exhaust muffler assy <i>1 1</i>	\$ 959.40 X
24	2	Rear exhaust muffler rubber mounting <i>1 1</i>	\$ 36.60 X
25	1	Rear end lower panel top garnish <i>1 1</i>	\$ 116.20 X
26	1	Rear left fender cowlings <i>1 1</i>	\$ 102.80 X
27	1	Rear right fender cowlings <i>1 1</i>	\$ 102.80 X
28	1	Rear left fender inner side garnish <i>1 1</i>	\$ 286.40 X
29	1	Rear right fender inner side garnish <i>1 1</i>	\$ 286.40 X
30	1	Rear windscreen glass moulding <i>1 1</i>	\$ 288.50 X
31	1	Rear spare tyre top cover <i>1 1</i>	\$ 177.60 X
32	1	Rear spare tyre top lock holder <i>1 1</i>	\$ 78.60 X
			\$ 4,939.50
Less 10%			\$ 493.95
			\$ 4,445.55

SGV9079R Nissan Latio

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10 1 set	Rear bumper clips <i>all</i>	\$ 60.00 <i>30</i>
2	4	Rear bootlid outer chrome moulding clips <i>all</i>	\$ 40.00 <i>X</i>
3	8	Rear bootlid inner trim board clips <i>all</i>	\$ 40.00 <i>X</i>
4	1	Rear left fender sealant <i>all</i>	\$ 100.00 <i>X</i>
5	1	Rear right fender sealant <i>all</i>	\$ 100.00 <i>X</i>
6	4	Rear left fender cowling clips <i>all</i>	\$ 20.00 <i>X</i>
7	4	Rear right fender cowling clips <i>all</i>	\$ 20.00 <i>X</i>
8	6	Rear left fender inner garnish clips <i>all</i>	\$ 30.00 <i>X</i>
9	6	Rear right fender inner garnish clips <i>all</i>	\$ 30.00 <i>X</i>
10	4	Rear end lower panel top garnish clips <i>all</i>	\$ 30.00 <i>X</i>
11	1	Rear end lower panel sealant <i>all</i>	\$ 120.00 <i>X</i>
12	1	Rear windscreen glass sealant <i>all</i>	\$ 100.00 <i>X</i>
13	1 1 set	Rear bumper reverse sensor <i>should</i>	\$ 300.00 <i>200</i>
14	1	Rear no plate with garnish <i>all</i>	\$ 100.00 <i>X</i>
15	1	Rear spare tyre floor panel sealant <i>all</i>	\$ 150.00 <i>X</i>
16	1	Rear spare tyre floor panel insulator pad <i>all</i>	\$ 180.00 <i>X</i>
			<u>\$ 1,420.00</u>

Total parts

\$ 8,981.32

LK K Auto Consultants hereby notify the Reparer of the following:

- To repair or replace damaged parts only
- To do any damaged part during recovery
- Parts prices are subject to confirmation
- Third party survey is a "Without Prejudice" loss
- No third modification is allowed
- Supplementary item(s) must be submitted and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

SGV9079R Nissan Latio

No	Labour Charge
1 Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,200.00 580
2 To putty and spray painting rear portion.	\$ 1,200.00 480
3 To check rear lighting and wiring.	\$ 50.00 30
4 To remove and install rear bootlid lock mechanism.	\$ 80.00 X
5 To remove and install rear exhaust muffler assy.	\$ 120.00 X
6 To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 X
7 To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 X
8 To apply anti rust proofing to rear affected area.	\$ 140.00 X
9 To remove and install rear bumper reverse sensor.	\$ 80.00 50
10 To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X
11 Towing service.	\$ 100.00 X
Total labour : \$ 3,430.00	

Total parts : \$ 8,981.32

Total labour : \$ 3,430.00

Total repair cost : \$ 12,411.32

9-556.90
 30%
 9-389.83
 S.N-230
 1-1140
 1759.83
 200
 14607.

LUK Auto Credit Centre hereby notify
 the Repairer of the following:
 • To remove and replace rear spray painting
 • To replace damaged parts during resurvey
 • Parts costs are subject to confirmation
 • Third party survey is on a "No Fault Pay" basis
 • No claim for loss of profit is allowed
 • Repairer agrees to indemnify the surveyor and
 company for any loss or damage to the vehicle and
 its contents.

Acknowledged by Repairer
 Signature:
 Date: