

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009723/AEA3Q2**Date:** 19/08/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLC7283X	Insured Vehicle No :	SLL6297R
Date of Loss:	14/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004077

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC7283X	Engine No:	G4FGGH612273
Make & Model:	KIA FORTE K3, 1.6 EX (A)	Chassis No:	KNAFX411MG5596032
Reg. Date:	25/05/2016 (Man. Year: 2016)	Odometer:	153655 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,616.28	4,359.89	1,256.39	22.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,260.00	810.00	39.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,686.28	5,619.89	2,066.39	26.88
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,686.28	4,500.00	3,186.28	41.45
+ GST 7.00/7.00% (S\$)	538.04	315.00	223.04	41.45
Nett Amount (S\$)	8,224.32	4,815.00	3,409.32	41.45
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,250.49		
Global Sum Settlement (S\$)		5,250.00		

INSPECTION

Date of Assignment:	16/09/2021	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	20/09/2021 Inspected At:	No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2022)
Parts:	143	KIA FORTE K3 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC7283X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Dented	485.60 FL	*485.60 FL
2	1		*FRT FENDER COWLING LH	Deformed	129.70 FL	*129.70 FL
3	1		*FRT BUMPER	Deformed	808.50 FL	*745.00 FL
4	1		*FRT BUMPER SIDE RETAINER LH	Necessary	29.40 FL	*29.40 FL
5	1		*HEADLAMP LH	Cut	2,057.00 FL	*2,057.00 FL
6	1		*FRT LOWER ARM LH	Bent	371.80 FL	*371.80 FL
7	1		*FRT KNUCKLE ARM LH	Not Necessary	414.70 FL	*- FL
8	1		*FRT SHOCK ABSORBER LH	Not Necessary	328.90 FL	*- FL
9	1		*FRT WHEEL HUB LH	Damaged	159.50 FL	*159.50 FL
10	1		*FRT WHEEL HUB BEARING LH	Damaged	144.10 FL	*144.10 FL
11	1		*SET FRT FENDER COWLING CLIPS LH	Necessary	40.00 FS	*35.00 FS
12	1		*SET FRT BUMPER CLIPS	Necessary	60.00 FS	*35.00 FS
13	1		*FRT RIM LH	Cut	800.00 FS	*580.00 FS
14	1		*FRT TYRE LH	Not Necessary	280.00 FS	*- FS
					Sub Total (S\$)	6,109.20 4,772.10
					- List Item Discount on L Items 10.00/10.00% (S\$)	492.92 412.21
					Total Parts (S\$)	5,616.28 4,359.89

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	(FRONT) TO SPRAY PAINTING	New	700.00	400.00
3	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS	New	700.00	500.00
4	TO REMOVE AND REFIT UNDERCARRIAGE	New	400.00	200.00
5	TO CHECK WHEEL ALINGMENT	New	120.00	80.00
6	TO SPRAY TUFF COAT	New	100.00	50.00
Gross Labour Cost (\$\$)			2,070.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >