

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62244174

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 14/09/2021

TP Veh Reg No: SLL6297R

Estimate No: EST2100238

Date: 16 Sep 2021

Veh Reg No: SLC7283X

Make/Model: KIA FORTE K3 1.6A EX

Chasis No: KNAFX411MG5596032

Reg. Date: 25/05/2016

Your Ref No: SLL6297R

Estimate Repair Cost to Vehicle No :SLC7283X

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC FRT FENDER LH <i>dent</i>	485.60 ✓	
2	1 PC FRT FENDER COWLING LH <i>dent</i>	129.70 ✓	
3	1 PC FRT BUMPER <i>dent</i>	808.50 745. ✓	
4	1 PC FRT BUMPER SIDE RETAINER LH <i>re</i>	29.40 ✓	
5	1 PC HEADLAMP LH <i>ct.</i>	2,057.00 ✓	1780
6	1 PC FRT LOWER ARM LH <i>But</i>	371.80 ✓	
7	1 PC FRT KNUCKLE ARM LH <i>3 in</i>	414.70 +	
8	1 PC FRT SHOCK ABSORBER LH <i>3 in</i>	328.90 +	
9	1 PC FRT WHEEL HUB LH <i>end</i>	159.50 ✓	
10	1 PC FRT WHEEL HUB BEARING LH <i>end</i>	144.10 ✓	
		4,929.20	
	Less 10%	492.92	4,436.28
Special Net			
11	1 SET FRT FENDER COWLING CLIPS LH <i>re</i>	40.00 ✓ 35	
12	1 SET FRT BUMPER CLIPS <i>re</i>	60.00 ✓ 35	
13	1 PC FRT RIM LH <i>ct.</i>	800.00 ✓ 580	
14	1 PC FRT TYRE LH <i>4 in re</i>	280.00 +	
		1,180.00	1,180.00
Labour			
15	1 TO CHECK WIRING	50.00 30	
16	1 (FRONT) TO SPRAY PAINTING	700.00 400	
17	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00 ✓ 500	
18	1 TO REMOVE AND REFIT UNDERCARRIAGE	400.00 280	
19	1 TO CHECK WHEEL ALIGNMENT	120.00 80	
	To spray buff coat	1,970.00	1,970.00

10650

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 14/09/2021
TP Veh Reg No: SLL6297R

Estimate No: EST2100238
Date: 16 Sep 2021

Veh Reg No: SLC7283X
Make/Model: KIA FORTE K3 1.6A EX
Chasis No: KNAFX411MG5596032
Reg. Date: 25/05/2016
Your Ref No: SLL6297R

Estimate Repair Cost to Vehicle No :SLC7283X

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 7,586.28
	Add GST @ 7%		531.04
	Total Amount Payable		<u>S\$ 8,117.32</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND ONE HUNDRED SEVENTEEN AND CENTS THIRTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
H/S 20/09/21.

05 Days.

Total: 5619.89

H/S 14.5K

(45K)