

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 14/09/2021
TP Veh Reg No: SLL6297R

Estimate No: EST2100238

Date: 16 Sep 2021

Veh Reg No: **SLC7283X**
Make/Model: KIA FORTE K3 1.6A EX
Chasis No: KNAFX411MG5596032
Reg. Date: 25/05/2016
Your Ref No: SLL6297R

Estimate Repair Cost to Vehicle No :SLC7283X

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC FRT FENDER LH	485.60	
2	1 PC FRT FENDER COWLING LH	129.70	
3	1 PC FRT BUMPER	808.50	
4	1 PC FRT BUMPER SIDE RETAINER LH	29.40	
5	1 PC HEADLAMP LH	2,057.00	
6	1 PC FRT LOWER ARM LH	371.80	
7	1 PC FRT KNUCKLE ARM LH	414.70	
8	1 PC FRT SHOCK ABSORBER LH	328.90	
9	1 PC FRT WHEEL HUB LH	159.50	
10	1 PC FRT WHEEL HUB BEARING LH	144.10	
		4,929.20	
	Less 10%	492.92	4,436.28
Special Net			
11	1 SET FRT FENDER COWLING CLIPS LH	40.00	
12	1 SET FRT BUMPER CLIPS	60.00	
13	1 PC FRT RIM LH	800.00	
14	1 PC FRT TYRE LH	280.00	
		1,180.00	1,180.00
Labour			
15	1 TO CHECK WIRING	50.00	
16	1 (FRONT) TO SPRAY PAINTING	700.00	
17	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00	
18	1 TO REMOVE AND REFIT UNDERCARRIAGE	400.00	
19	1 TO CHECK WHEEL ALIGNMENT	120.00	
		1,970.00	1,970.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 14/09/2021
TP Veh Reg No: SLL6297R

Estimate No: EST2100238

Date: 16 Sep 2021

Veh Reg No: **SLC7283X**
Make/Model: KIA FORTE K3 1.6A EX
Chasis No: KNAFX411MG5596032
Reg. Date: 25/05/2016
Your Ref No: SLL6297R

Estimate Repair Cost to Vehicle No :SLC7283X

Quantity	Description	List Price	Amount
		S\$	S\$
		Total	S\$ 7,586.28
		Add GST @ 7%	531.04
		Total Amount Payable	S\$ 8,117.32

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND ONE HUNDRED SEVENTEEN AND CENTS
THIRTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE