

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

15-Sep-21

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8098 K

1 pc	Front bumper	\$	811.11	X repair
		\$	811.11	
	Less 20%	\$	162.22	
		\$	648.89	

### S/NETT

1 set	Front bumper clips	\$	48.00	✓ nil
1 pc	Front number plate & holder	\$	50.00	✓ C/A
	Sundry	\$	50.00	X Svc

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same, etc

\$ 250.00 180

To putty and spray painting on the front bumper

\$ 250.00 180

Total \$ 1,296.89

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

F: \$458

2 repair days

Thuan @ khanto. com

82 235769

2 days w/p

P/P after repair photo

20/9/21 1445

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: