

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21009725/UES3Q2
Date: 18/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993609
Claimant Vehicle No :	FBH3583Z	Insured Vehicle No :	SLH9495L
Date of Loss:	11/09/2021	Nature of Claim:	TP
		Claim No:	7053275535SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH3583Z	Engine No:	KB612752
Make & Model:	SYM GTS 200, 172cc	Chassis No:	RFGLM18WXDS002117
Reg. Date:	21/05/2013 (Man. Year: 2013)	Odometer:	973662 km
Colour:	Silver		
Engine Capacity:	172 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/90-13	Rear Tyre Size:	130/70-12
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,005.10	2,777.50	3,227.60	53.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	730.00	420.00	36.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,155.10	3,507.50	3,647.60	50.98
Approved Total (Overridden) (S\$)		2,700.00		

Nett Amount (S\$)	7,155.10	2,700.00	4,455.10	62.26
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		2,820.00		

INSPECTION

Date of Assignment: 16/09/2021

Date Inspected: 16/09/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FAIRING	Cracked	495.00 FL	*495.00 FL
2	1		*FRONT FAIRING INNER PANEL	Cracked	280.00 FL	*280.00 FL
3	1		*FRONT LOWER FAIRING	Cracked	220.00 FL	*220.00 FL
4	1		*HEADLAMP	Serviceable	250.00 FL	*- FL
5	2		*FRONT SIGNALS	Not Necessary	330.00 FL	*- FL
6	1		*FRONT MUDGUARD	Repair	180.00 FL	*- FL
7	1		*FRONT FORK ASSY	Serviceable	980.00 FL	*- FL
8	1		*FORK UNDER BRACKET	Not Necessary	230.00 FL	*- FL
9	1		*FRONT RIM	Not Necessary	320.00 FL	*- FL
10	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
11	1		*LOWER BELLY PANEL	Cracked	285.00 FL	*285.00 FL
12	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
13	1		*WINDSHIELD	Cracked	180.00 FL	*180.00 FL
14	1		*SIDE MIRRORS	O/S Cut	220.00 FL	*60.00 FL
15	1		*HANDLE BAR	Bent / Twisted	165.00 FL	*125.00 FL
16	1		*SET HAND GRIP	Not Necessary	78.00 FL	*- FL
17	2		*HANDLE BAR ENDS	Missing / Twisted	80.00 FL	*80.00 FL
18	1		*AIR FILTER BOX	Cut	185.00 FL	*185.00 FL
19	2		*BRAKE LEVERS	Serviceable	98.00 FL	*- FL
20	1		*REAR FAIRING -L/H	Cracked	435.00 FL	*435.00 FL
21	1		*FOOTSTEP PANEL	Cracked	155.00 FL	*155.00 FL
22	1		*SIDE STAND	Not Necessary	78.00 FL	*- FL
23	1		*MAIN STAND	Not Necessary	120.00 FL	*- FL
24	1		*REAR FOOTREST	Twisted	105.00 FL	*90.00 FL
25	1		*REAR FOOTREST BRACKET	Twisted	185.00 FL	*185.00 FL
26	1		*SET NUMBER PLATE	Frt Necessary	38.00 FS	*10.00 FS
27	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
28	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
29	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
30	1		*REAR BOX	Cut	350.00 FS	*220.00 FS
31	1		*REAR BOX BRACKET	Serviceable	100.00 FS	*- FS
32	1		*GST 200 STICKER	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,593.00	3,055.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	587.90	277.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						6,005.10
						2,777.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE(LOD)	New	50.00	30.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	300.00
4	TO RESPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (S\$)			1,150.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >