

(05/11/13) Wef
ASS. REC. BY: Marcus

REF:

CC4/A1921009725/4es3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBH 35832
at Workshop m/s Enoia
of _____

Insured: SLH 9495L

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 3k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: LTA \$285

Vehicle: IN / OUT

Date / Time Action / Instruction Dep 1900
met 2715

Veh No: FBH 35832 Yr Regn: 21/5/13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SYM GTS200 C/C 172

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 973662 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RFGLM18WXD5002117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SDRim / STD A/Rim or

Tyre Size: F: 110/90-13 P.R
R: 130/70-12 maxx15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. 11/9/14 D.O.I. 16/9/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S, O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

12/10/14 4/5 & 2700 confirmed with mr Teo.

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

E-mail: erofia@singnet.com.sg

A16

Name : Mohamed Niyaz (82452526)

Accident Date : 11-Sep-21

Vehicle No : FBH3583Z

Vehicle Model : SYM GTS200

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fairing <i>ena ✓</i>	\$ 495.00 ✓
1	Front fairing inner panel <i>ena ✓</i>	\$ 280.00 ✓
1	Front lower fairing <i>ena ✓</i>	\$ 220.00 ✓
1	Headlamp <i>sve X</i>	\$ 250.00 X
2	Front signals <i>1-1 X</i>	\$ 330.00 X
1	Front mudguard <i>R X</i>	\$ 180.00 X
1	Front fork assy <i>sve X</i>	\$ 980.00 X
1	Fork under bracket <i>1-1 X</i>	\$ 230.00 X
1	Front rim <i>1-1 X</i>	\$ 320.00 X
1	Front brake disc <i>1-1 X</i>	\$ 180.00 X
1	Lower belly panel <i>ena ✓</i>	\$ 285.00 ✓
1	Front rim shaft <i>1-1 X</i>	\$ 45.00 X
1	Windshield <i>ena ✓</i>	\$ 180.00 ✓
2	Side mirrors <i>015 411 pc 62</i>	\$ 220.00 1 pc
1	Handle bar <i>Bent/TWI 125</i>	\$ 165.00 ✓
1	Hand grip (1 set) <i>1-1 X</i>	\$ 78.00 X
2	Handle bar ends <i>m.s / TWI ✓</i>	\$ 80.00 ✓
1	Air filter box <i>ca 7 ✓</i>	\$ 185.00 ✓
2	Brake levers <i>sve X</i>	\$ 98.00 X
1	Rear fairing - L/H <i>ena ✓</i>	\$ 435.00 ✓
1	Footstep panel <i>ena ✓</i>	\$ 155.00 ✓
1	Side stand <i>1-1 X</i>	\$ 78.00 X
1	Main stand <i>m X</i>	\$ 120.00 X
1	Rear footrest <i>twi ✓</i>	\$ 105.00 ✓
1	Rear footrest bracket <i>twi ✓</i>	\$ 185.00 ✓
		\$ 5,879.00
	Less 10%	\$ 587.90
		\$ 5,291.10

Ns / Ahmad
Lee

16/9/21

1/5 \$2700
Hdngs Take place after rep.

2775
103
2497.5

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

E-mail: erofia@singnet.com.sg

Name : Mohamed Niyaz (82452526)

Accident Date : 11-Sep-21

Vehicle No : FBH3583Z

Vehicle Model : SYM GTS200

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>fine</i>	\$	38.00 <i>10</i>
2	Fork oils <i>and</i>	\$	30.00 <i>X</i>
2	Fork oil seals <i>and</i>	\$	56.00 <i>X</i>
1	Steering cone (1 set) <i>and</i>	\$	90.00 <i>X</i>
1	Rear box <i>CMT 220</i>	\$	350.00 <i>220</i>
1	Rear box bracket <i>su X</i>	\$	100.00 <i>X</i>
1	"GTS 200" sticker <i>su</i>	\$	50.00 <i>✓</i>
		\$	<u>714.00</u>

S/No. Labour

1	To provide towing service (LOD)	\$	50.00 <i>30</i>
2	To check wiring and reset headlamp focusing	\$	<i>11</i> 80.00 <i>X</i>
3	To provide labour	\$	420.00 <i>300</i>
4	To respray painting	\$	600.00 <i>400</i>
		\$	<u>1,150.00</u>

Grand Total

\$ 7,155.10

Dollars: Seven Thousand One Hundred Fifty-Five and Cents: Ten only


EROFIA MOTOR TRADING PTE LTD

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3807.5