

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBC2730Z

TPA16.

Model:

TOYOTA DYNA

Accident Date : 15/9/2021

Cecilia.

(17/13/2011)

Location : CHOA CHU KANG DR ENTERING KJE

3P:

SML9077C (AIG)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tail-gate '70 km/h' sticker <i>New</i>		20.00 15	
2	1 pc	Rear tail-gate o/s stopper bracket <i>Reps</i>	110.00	x.	
3	1 pc	Rear o/s tail-lamp <i>crackd</i>	270.50	✓	
4	1 pc	Rear fiber glass <i>crackd</i>		2,000.00 700 (S.W.)	
		270.50 S.N: 715 Sub-Total:	380.50	2,020.00	0.00
		202.87 After Less %:	25%	0%	0%
			285.38	2,020.00	0.00
		Labour			
1		To remove and replac rear damage parts	800.00	200	
2		To spray painting.	700.00	400.	
3		To check wiring.	50.00	30	
		630 Sub-Total:	1,550.00		
		Total:	3,855.38		
		After Less 20%:	3,084.30		

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

Adrian

A/S 20/09/21.

03 Days.



AL 8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Label: 1547.87

L/S: 1.2k