From: Date: Veh No: SIAD 97627 YER	
From: Date: Veh No. Cut 97/27	
Type: M.Car/ M.Colo/ Dura War 1	legn: <u>  0   2 0</u> 
Truck / Trailer or	
To Inspect Vehicle No:  Make: Toy Privs	c.c 1798
at workshop m/s Cab Colour M. P. White IRI AKC:	Insured / Std / NI / NA
	o: Insured / Std / NI / NA
Insured: Eng/No:	
Policy No. TTDKB 31-4 0	03092403
Claims No Gen. Cond: Good / Fair / Poor / Burnt	
Sum Insured: Excess: Steering: Inorger? Jammed / Leaked / Burnt or	
(Client's Record)  Brake: Inorder / Jammed / Leaked / Burnt or	
Make of Veh: Modi: Nii / S/Rim / STD A/Rim or	
	185R15
(Policy Condition)  R: Dun	
Remark: The veh had commenced its  N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTS  repair at the time of inspection.	SU / PIR / SUMI /
1010/10K8 or	***************************************
Bal. or Market Value: Front Rear	
IDAC Accident Rport: Consistent?: Yes or No R/Bal. mm R/Bal.	Z mm
GIA / PR Seen: Consistent?: Yes or No L/Bal. 1/Bal.	2 mm
Est. Repairs: 06 days Res.: Yes or No D.O.A. 14/9/2, D.O.I.	15/9/2021
Lum Sum:/ % 3 Val.: Yes or No Survey held at	
CA / REV / REP. / 24 HRS Des. of Damages: Frt / Rear / O/S / N/S / U/C	
Date: Person Contacted: Vehicle: IN/OUT US body & N/S /	
Date / Time   Action / Instruction   The U/C / Chassis frame / Body Structure at	ffected due to collision.
RED	
CONFIRM FINALISE AT \$12032.25,6DAYS	
RED: 12,368.08; 50%	
IXED: 12,300:00, 3070	
	-
Data/Tirro, File Pass 10?	
Days Of Repair:	
1) Resurvey No. of Trip: Survey Fee:	: [
Transporta65vii	:
Add Fee: Site Insp (\$ )_s-Rs_	SI
: Interview (\$ ) Fartos	
Report Format: Tech Invs (\$ ) Others	
Lump Sum / I.B.I: (S ) Weekend (\$ )	
TOTAL	

# **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9762J

Not Norhanks
Resony B& paint

		Vohiala N				
		Vehicle No.:			SH	D9762J
		Chassis No.:	15 SEP 2021		JTE	DKB3FU903091511
		Vehicle Make:	R. Ang		TO	YOTA
		Vehicle Model:		4	PR	IUS GEN 4
		Date of Accident :			14/	/09/2021
		Third Party Insurer:			EC	ICS **
		Date of Registration:			30/	10/2020
	1	COVER FROME PART				LIST
	1	THE THE POWER			\$	By 521.00
		WITH A LICE MICHAIL SOR-W224' LKOMI ROW	IPER		\$	716.60 7
	1	WELL TO THE ELLIPTING THE POWINER, NO.2			\$	246.10 7
	1	ABSORBER, FRONT BUMPER, LOWER			\$	132.70
	1	ABSORBER, FRONT BUMPER ENERGY			\$	80.20
	1	EXTENSION, FRONT BUMPER, LH			\$	120.10 7
	*1	MOULDING, FRONT BUMPER SIDE, LH			\$	cm 95.60 -
	1	BRACKET, FRONT BUMPER SIDE, LH			\$	Dir 59.30
	1	JAR ASSY, WINDSHIELD WASHER			\$	1 219.10 X
	1	UNIT ASSY, HEADLAMP, LH		3	\$	cm 2,637.60 —
	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO	0.1		\$	5m 3,772.50 X
	1	LAMP ASSY, FOG, LH			\$	237.10 🕶
	1	GRILLE SUB-ASSY, RADIATOR 32.25, 6DAY	'S0		\$	422.50 ×
	1	GRILLE, RADIATOR, LOWER NO.1			\$	W 178.60 -
	1	EMBLEM ASSY, RADIATOR GRILLE			\$	ne 105.80 —
	1	COVER SUB-ASSY, ENGINE UNDER, NO.2			\$	241.90 X
	1	BRACE SUB-ASSY, DASH TO FRAME, LH			\$	182.20
	1	COVER SUB-ASSY, FRONT PILLAR, UPR LH			\$	h 100.40 X
	1	FENDER SUB-ASSY, FRONT LH			\$	977.80
	1	LINER, FRONT FENDER, LH			\$	cm 210.30
	1	EMBLEM, SIDE PANEL, LH			¢	Mr. 54.50
	1	FENDER SUB-ASSY, FRONT RH			\$	Ma 54.60 -
	1	LINER, FRONT FENDER, RH			\$	977.80 <u></u>
ŗ,	1	EMBLEM, SIDE PANEL, RH			\$	202.50 X
	1 .	PANEL SUB-ASSY, FRONT DOOR, RH			\$	Ma 54.60
		LOCK ASSY, FRONT DOOR W/MOTOR, RH				By 1,300.70 —
					Ф	€ 603.20 ×

#### **Trans-cab Auto Services Pte Ltd** No. 2 Ang Mo Kio Street 63 Singapore 569111 AAD2109-063 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G SHD9762J MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH 1 In 38.60 X \$ FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH 1 \$ 193.50 7 HANDLE ASSY, FRONT DOOR, OUTSIDE RH 1 Der 390.60 \$ MOTOR ASSY, POWER WINDOW REGULATOR, RH 1 926.00 7 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH 1 1 321.10 X HINGE ASSY, FRONT DOOR, LOWER RH 1 7 110.60 X HINGE ASSY, FRONT DOOR, UPPER RH 1 n 97.50 x REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH 1 238.30 7 1 TAPE, BLACK OUT, NO.2 FRT RH Ma 43.50 -1 TAPE, BLACK OUT, NO.1 FRT RH na 13.30 — 1 TAPE, BLACK OUT, NO.3 FRT RH Ma 26.30 -PANEL SUB-ASSY, REAR DOOR, RH 1 1,294.90 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH 1 ° 193.50 X HANDLE ASSY, REAR DOOR OUTSIDE, RH 1 97.40 X WEATHERSTRIP, REAR DOOR OPENING TRIM, RH 1 ~ 293.00 X MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH 1 926.00 7 1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH 206.70 7 1 TAPE, BLACK OUT, NO.2 REAR RH May 34.90 -1 TAPE, BLACK OUT, NO.3 REAR RH ne 15.40 -1 TAPE, BLACK OUT, NO.1 REAR RH Ma 21.90 \_ 1 HINGE ASSY, REAR DOOR, LOWER RH N 87.10 ⊀ 1 HINGE ASSY, REAR DOOR, UPPER RH 1 98.90 X 1 PANEL SUB-ASSY, QUARTER, RH R 871.50 X \$ 1 LINER, REAR WHEEL HOUSE, RH In 139.80 K 1 MOULDING ASSY, BODY ROCKER PANEL, RH 594.80 X TOTAL \$ 21,725,90 25% \$ 5,431.48 \$ 16,294,43 **Special Nett**

X	FRT FENDER LINER CLIP	\$ ne 130.00 4
1	REAR BUMPER RETAINER CLIP	\$ " 75.00 X
1	FRT BUMPER CLIP	\$ Mr 75.00 500a-
1	HUB CAP	\$ 5h 211.50 x
1	RIM	\$ Des 1,879.40

Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G			AAD2109-063
SHD9762J			
1SET CLIP, ROCKER PANEL MOULDING		\$	~~ 65.00 X
2 DOOR STICKER TRANSCAB		\$	nec 200.00 120/ne
1 DOOR STICKER TEL. NO	TOTAL	\$	ner 100.00 605~
2SET DOOR TRIM CLIP		\$	~~ 140.00 <del>∠</del>
2SET DOOR WEATHERSTRIP CLIP	Over All Ton	\$	~~ 130.00 X
Ave A house many one	TOTAL	\$	3,005.90
(4-94401 - \$1.8 - %)	and repair Day	3	34
	TOTAL PARTS	\$	19,300.33
LABOUR			
To Rust-Proofing and apply undercoat Of The	Affected Areas.	\$	240.00 1201
To remove and refit interior fittings, trimings, gand other, to enable repair.	garnish, fittings	\$	NN 380.00 X
Panel Beating, Knocking And Straightening The			
Portion, Remove And Renewal Of Parts, Adjust Same	And Realign The	\$	1,600.00 Faal
To transfer of rear end panel fittings, attachme	nt to facilitate	the Dethorac	
bodywork repair.		\$	12 380.00 X
Putty And Spray Painting Of The Affected Porti	on.	\$	1,600.00 1540[
To reinstall rear bumper parking sensor.		\$	Nn 170.00 X
To transfer of tire, rim and on wheel balancing.		\$	170.00 201
To Check Electrical Lighting Concerned.		\$	170.00 201
To check steering geometry and computer whe	el alignment	\$	220.00 60/

# **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD9762J

To remove and refit of rear fender fittings, attachment and perform water seepage test.

Nn 170.00 X TOTAL \$ 5,100.00

Over All Total \$

24,400.33

AAD2109-063

(PART-BY-PART) Repair Days

CONFIRM \$12,032.25, 6DAYS

# LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to reputient policy liability.
 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for Investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission 14/09/2021 19:56 (SGT) Date of Accident 14/09/2021 14:45 (SGT) Exact Location of Accident Singapore Additional Location Information ALONG ANG MO KIO AVE 3 BEFORE JUNCTION OF ANG MO KIO AVE 6 OPP ANG MO KIO HUB Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SHD9762J

#### INSURED/POLICYHOLDER

Is company? Name Of Registered Owner TRANS-CAB SERVICES PTE LTD Company Reg No 2XXXXX878K Email Address claims@transcab.com.sg Mobile Phone No (Phone) +65-62876666 Alternative Phone No (Office) +65-62876666

## VEHICLE PARTICULARS

Toyota Model ..... Prius Exact purpose for which vehicle was being used at time of accident Private hire Are you claiming under your own insurance policy for repair to your vehicle? ...... No - Claiming third party Vehicle Category Taxi Transmission Auto 1767

## INSURANCE COMPANY


Name of Insurance Company ..... AXA Insurance Pte Ltd Type of Coverage ThirdParty Fleet Policy Yes Policy Number VFX/P2413997 Cover Note Number

DRIVER

LIM PHUAY HENG

Accident report SA0A219E0007

Page 1 of 13



#### **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD ON THE CENTER LANE. AS I APPROACHED THE TRAFFIC LIGHT, IT WAS STILL GREEN AND I PROCEEDED NORMALLY. AS I PASSED THE STOP LINE, SUDDENLY VEHICLE B, COMING FROM A MINOR ROAD ON MY RIGHT, AT THAT JUNCTION, MAKING A FAST RIGHT TURN AND CAME STRAIGHT TOWARDS MY VEHICLE. AND HIT THE RIGHT PORTION OF MY VEHICLE. THE IMPACT PUSHED MY VEHICLE TO MY LEFT AND HIT VEHICLE C, WHICH WAS TRAVELLING ON THE EXTREME LEFT LANE. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

CONFIRM FINALISE AT \$12032.25,6DAYS RED: 12368.08

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time: VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
HASHIM BIN KAMARI

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

2