

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9762J**AAD2109-063***Not Authen**Running Bk paint**814061-70*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 SEP 2021**SHD9762J**

JTDCB3FU903091511

TOYOTA

PRIUS GEN 4

14/09/2021

ECICS

30/10/2020

PART		LIST	
1	COVER, FRONT BUMPER	\$	B 521.00 ✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	B 716.60 ✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	R 246.10 X
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM 132.70 ✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	SM 80.20 X
1	EXTENSION, FRONT BUMPER, LH	\$	SM 120.10 X
1	MOULDING, FRONT BUMPER SIDE, LH	\$	CM 95.60 ✓
1	BRACKET, FRONT BUMPER SIDE, LH	\$	DR 59.30 ✓
1	JAR ASSY, WINDSHIELD WASHER	\$	SM 219.10 X
1	UNIT ASSY, HEADLAMP, LH	\$	CM 2,637.60 ✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	SM 3,772.50 X
1	LAMP ASSY, FOG, LH	\$	SM 237.10 X
1	GRILLE SUB-ASSY, RADIATOR	\$	SM 422.50 X
1	GRILLE, RADIATOR, LOWER NO.1	\$	CM 178.60 ✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	SM 105.80 ✓
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	SM 241.90 X
1	BRACE SUB-ASSY, DASH TO FRAME, LH	\$	R 182.20 X
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	SM 100.40 X
1	FENDER SUB-ASSY, FRONT LH	\$	B 977.80 ✓
1	LINER, FRONT FENDER, LH	\$	CM 210.30 ✓
1	EMBLEM, SIDE PANEL, LH	\$	SM 54.60 ✓
1	FENDER SUB-ASSY, FRONT RH	\$	B 977.80 ✓
1	LINER, FRONT FENDER, RH	\$	SM 202.50 X
1	EMBLEM, SIDE PANEL, RH	\$	SM 54.60 ✓
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	B 1,300.70 ✓
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	R 603.20 X

Front grille

Front grille beam

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2109-063

SHD9762J

1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	Sm	38.60	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	Sm	193.50	X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	Del	390.60	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	Sm	926.00	X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	Sm	321.10	X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R	110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R	97.50	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	Sm	238.30	X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	Sm	43.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	Sm	13.30	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	Sm	26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	Sm	1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	Sm	193.50	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	Sm	97.40	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	Sm	293.00	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	Sm	926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	Sm	206.70	X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	Sm	34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	Sm	15.40	✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	Sm	21.90	✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R	87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	R	98.90	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	R	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	Sm	139.80	X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	Sm	594.80	X
TOTAL		\$		21,725.90	
25%		\$		5,431.48	
		\$		16,294.43	

Special Nett

✓	FRT FENDER LINER CLIP	\$	Sm	130.00	✓ 65.00
1	REAR BUMPER RETAINER CLIP	\$	Sm	75.00	X
1	FRT BUMPER CLIP	\$	Sm	75.00	50.00
1	HUB CAP	\$	Sm	211.50	X
1	RIM	\$	Del	1,879.40	✓

Headlamp control

Front grille

Front grille beam

1

cm 185.00

185.00

Trans-cab Auto Services Pte Ltd

AAD2109-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9762J

1SET CLIP, ROCKER PANEL MOULDING

2 DOOR STICKER TRANSCAB

1 DOOR STICKER TEL. NO

2SET DOOR TRIM CLIP

2SET DOOR WEATHERSTRIP CLIP

\$	nn	65.00	X
\$	nn	200.00	1201
\$	nn	100.00	605N
\$	nn	140.00	X
\$	nn	130.00	X
TOTAL	\$	3,005.90	

TOTAL PARTS \$ 19,300.33**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	1201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	7001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	15401
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	220.00	601

31 Headlamp

32 Front grille

33 Front grille beam

1

cm 185.00

185.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9762J

To remove and refit of rear fender fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X
TOTAL \$ **5,100.00**

Over All Total \$ **24,400.33**

(PART-BY-PART) Repair Days **20 Days**

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: