

Steve (LKK)
17/9/21, 2.30pm

AD-M AL
EXHIBIT-?
P/P
M BIL Sy
3 days

44728 - C00001 SL: SERVICE SALES - PC
ROCHE DIAGNOSTICS ASIA PACIFIC PTE LTD
Attn: Mr Anton Gutscher
214 Ocean Drive
Singapore 098623

GST Reg.No: M28920628X
Inv.No. : B&P 0 Page 1
Inv.date. : 17/09/2021
WIP No. : 46181
Veh.In/Out:
*Tel.No. : Work: 63716632
Reg.No. : SKJ477A
Reg.date : 07/02/2013
Mileage : 0
Chassis No: SALVA2AGXDH727432

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : ROCHE DIAGNOSTICS AS

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, BUMPER BEAM, ETC	0	1300	2000.00	0		2,000.00	S
800	TO SPRAYPAINT ON FRT BUMPER	0	1000	1800.00	0		1,800.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		621.00	0		621.00	S
R06	NUMBER PLATE & HOLDER	0		60.00	0		60.00	S
	BUMPER COVER FRT EVO	1.0	EA	2081.20			2,081.20	S
	BUMPER BEAM FRT EVOQ	1.0	EA	1119.70			1,119.70	S
	BUMPER BRACKET FRT C	1.0	EA	506.80			506.80	S
							1873.08	
							1007.73	
							456.12	

Gross Total. 8,188.70
Net..... 8,188.70
GST @ 7.0% 573.21
Total..... 8,761.90
Paid..... 0.00
Please Pay.. 8,761.90

Labour Total 4,481.00
Parts Total 3,707.70
Package Total 0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage to parties during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no: 199501400R / GST reg no. M28920628X
Date: