

SERVICE ESTIMATE

44728 - C00001 SL: SERVICE SALES - PC
 ROCHE DIAGNOSTICS ASIA PACIFIC PTE LTD
 Attn: Mr Anton Gutscher
 214 Ocean Drive

Singapore 098623

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : ROCHE DIAGNOSTICS AS

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 15/11/2021
 WIP No. . : 46181
 Veh.In/Out: 11/11/2021 15/11/2021
 *Tel.No. . : Work: 63716632
 Reg.No. . : SKJ477A
 Reg.date . : 07/02/2013
 Mileage . : 98,440
 Chassis No: SALVA2AGXDH727432

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER,	0	1300.00	0		1,300.00	S
	BUMPER BEAM, ETC						
800	TO SPRAYPAINT ON FRT BUMPER	0	1000.00	0		1,000.00	S
280	TO CHECK WIRING INCLUDE	0	621.00	0		621.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
EXC	Excess cost	0	2000.00	0		-2,000.00	S
	BUMPER COVER FRT EVO	1.0 EA	2081.20	10		1,873.08	S
	BUMPER BEAM FRT EVOQ	1.0 EA	1119.70	10		1,007.73	S
	BUMPER BRACKET FRT C	1.0 EA	506.80	10		456.12	S

Labour Total 2,981.00
 Parts Total 3,336.93
 Package Total 0.00

Gross Total. 6,317.93
 Less..... 2,000.00
 Net..... 4,317.93
 GST @ 7.0% 302.26
 Total..... 4,620.20
 Paid..... 0.00
 Please Pay.. 4,620.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated