

SERVICE ESTIMATE

44728 - C00001 SL: SERVICE SALES - PC
 ROCHE DIAGNOSTICS ASIA PACIFIC PTE LTD
 Attn: Mr Anton Gutscher
 214 Ocean Drive

Singapore 098623

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : ROCHE DIAGNOSTICS AS

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 26/11/2021
 WIP No. . : 46181
 Veh.In/Out: 11/11/2021 15/11/2021
 *Tel.No. . : Work: 63716632
 Reg.No. . : SKJ477A
 Reg.date . : 07/02/2013
 Mileage . : 98,440
 Chassis No: SALVA2AGXDH727432

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER,	0		1300.00	0		1,300.00	S
	BUMPER BEAM, ETC							
800	TO SPRAYPAINT ON FRT BUMPER	0		1000.00	0		1,000.00	S
280	TO CHECK WIRING INCLUDE	0		621.00	0		621.00	S
	RESETTING OF ALL ELECTRICAL							
	MODULES							
R06	NUMBER PLATE & HOLDER	0		60.00	0		60.00	S
EXC	Excess cost	0		2000.00	0		-2,000.00	S
EXC	Excess cost	0		500.00	0		-500.00	S
	BUMPER COVER FRT EVO	1.0	EA	2081.20	10		1,873.08	S
	BUMPER BEAM FRT EVOQ	1.0	EA	1119.70	10		1,007.73	S
	BUMPER BRACKET FRT C	1.0	EA	506.80	10		456.12	S

				Gross Total.	6,317.93
				Less.....	2,500.00
				Net.....	3,817.93
				GST @ 7.0%	267.26
				Total.....	4,085.20
				Paid.....	0.00
				Please Pay..	4,085.20
Labour	Total	2,981.00			
Parts	Total	3,336.93			
Package	Total	0.00			

GST: S=StdRated; O=OutOfScope; Z=ZeroRated