



SURVEYORS & ADJUSTERS

ARC CLAIMS CONSULTANCY SURVEY REPORT

TO **A L Motorwerkz** PAGES : 3
25 Kaki Bukit Road 4 DATE : 31.08.2021
#03-62 OUR REF ARC/2021-015
Singapore 417800

REFERENCE & PARTICULARS

VEHICLE : FBR 7500J
INSURED OWNER : LYE MOH SHE, MOSES AARON
POLICY NO : NA
CLAIM NO : NA
ACCIDENT DATE : 27.07.2021 13:25HRS

THIRD PARTY CLAIM

INSPECTION REQUESTED : OWNER
ASSIGNMENT DATE : 30.07.2021
SUM INSURED : NA
EXCESS AMOUNT : NA

PARTICULARS OF DAMAGED VEHICLE:

MAKE/MODEL	: YAMAHA XSR155 MANUAL	PRE-ACCIDENT STATUS	: GOOD
YEAR	: 2020	STEERING	: GOOD
CAPACITY	: 155CC	BRAKES	: GOOD
ENGINE NO	: G3J6E0278364	MILEAGE	: TBA
CHASIS NO	: MH3RG4760LK009154	COLOUR	: BLACK

TYRE CONDITION : SIZE (FRONT): - SIZE (REAR):-

FRONT REMAINING THREADS : -

REAR REMAINING THREADS : -

GENERAL DESCRIPTION OF DAMAGE

Main Body, Left Rear, Right Rear

INSPECTION DETAILS

SURVEY HELD AT : 25 Kaki Bukit Road 4
#03-62 Singapore (417800)
PHOTOGRAPHS : 28 INSPECTION DATED : 30.07.2021


REMARKS : (SUBJECT TO POLICY CONDITION)

THIS SURVEY WAS CONDUCTED STRICTLY "WITHOUT PREJUDICE"
ESTIMATED NORMAL PERIODS OF REPAIRS (14) WORKING DAYS

4

IN ACCORDANCE WITH YOUR INSTRUCTIONS, WE HAVE
AUTHORISED REPAIRS. (This estimate covers visible damages only.)

Should there be any discrepancy or unseen items in this survey, kindly notify the





SURVEYORS & ADJUSTERS

VEHICLE NO : FBR 7500J

POLICY NO :

CLAIM NO :

OUR REF : ARC/2021-015

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS :

S/N	QTY	DESCRIPTION (MATERIAL ITEMS)	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	-----	---------------------------------	------------------------	-----------------------	----------------------

LABOUR

1		To remove and replace damaged parts and components		540.00	486.00 150 ✓
2		To remove, refix wiring system at accident damaged areas		72.00	64.80 30 ✓
3		Transport motorcycle to workshop for repairs		72.00	30 64.80 ✓

Labour Total : 684.00 615.60

TOTAL (PARTS & LABOUR): 4,718.05

NETT TOTAL 4,718.05

AGREED AT LUMP SUM 4,500.00

800 ✓

4 DAYS



SURVEYORS & ADJUSTERS

VEHICLE NO : FBR 7500J

POLICY NO :

CLAIM NO :

OUR REF : ARC/2021-015

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS :

S/N	QTY	DESCRIPTION (MATERIAL ITEMS)	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
<u>PARTS(LIST ITEMS)</u>					
1	1	Front LH balancer	Grazed	156.00	140.40
2	1	Front brake level	Bent	143.00	128.70
3	1	Rear tail mudflat	Distored	273.00	245.70
4	1	Rear taillamp	Cracked	364.00	327.60
5	1	Rear tail fender	Cracked	318.50	286.65
6	1	Rear exhuaust pipe	Grazed	3,120.00	2,808.00
7	2	Rear LH & RH side lamp @\$60	Damaged	156.00	140.40
TOTAL PARTS (LIST):				4,530.50 less 10%	4,077.45
<u>SPECIAL NETT ITEMS</u>					
8	1	Rear number plate	Bent	25.00	25.00
TOTAL PARTS(SPECIAL NETT)				25.00	25.00
TOTAL PARTS:					4,102.45