



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

STRIDES AUTOMOTIVE SERVICES PTE LTD

INV No. AC2105808

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV Date 17/08/2021

Reference CS3/SMR21008231/Vuf3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. FBR 7500J

Insured Veh. SHD 6171J

Claim No. TAX/07/21/2059

Policy No.

Accident Date 27/07/2021

Inspection Date 06/08/2021



Description	Total
Pre-Repair Survey	128.00
Subtotal	128.00
GST (7%)	8.96
Grand Total	136.96

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21008231/Vuf3e2 Date: 17/08/2021 Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHD 6171J	Veh. Inspected	FBR 7500J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/07/21/2059	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	04/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA XSR155	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MH3RG4760LK009154	Colour	BLACK	
Odometer		Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	100/90 R17	BRIDGESTONE	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	100/90 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	27/07/2021	Inspect Date / Time	06/08/2021 (02:45 PM)	
Survey held at	BEAR'S GARAGE LLP 25 KAKI BUKIT ROAD 4 #03-62 SYNERGY@KB SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/SMR21008231/Vuf3e2

Inspected By



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBR 7500J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

