

28	AIR CON CONDENSOR TOP BRACKET	2	\$ 25.00	\$ 50.00
29	AIR CON FAN BLADE	1	\$ 98.90	\$ 98.90
30	AIR CON FAN MOTOR	1	\$ 498.20	\$ 498.20
31	AIR CON FAN COWLING	1	\$ 189.70	\$ 189.70
32	AIR CON FAN COWLING (SUCTION)	1	\$ 129.60	\$ 129.60
33	AIR CON PIPE (PRESSURE)	1	\$ 299.90	\$ 299.90
34	RADIATOR	1	\$ 1,507.40	\$ 1,507.40
35	RADIATOR SIDE GARNISH	2	\$ 45.00	\$ 90.00
36	RADIATOR TOP BRACKET	2	\$ 32.00	\$ 64.00
37	RADIATOR MOUNTING	4	\$ 12.00	\$ 48.00
38	RADIATOR SPARE TANK	1	\$ 93.80	\$ 93.80
39	ABS PUMP	1	\$ 1,897.90	\$ 1,897.90

5889.50

4711.60

TOTAL PRICE \$ 14,037.00
 LESS 20% \$ 2,807.40
SUB TOTAL PRICE \$ 11,229.60

1942.9
 5889.5
 1177.9
 4711.6

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER SIDE BOTTOM GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
3	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00
4	FRONT SUPPORT PANEL SEALANT	1	\$ 80.00	\$ 80.00
5	RADIATOR SIDE GARNISH LH CLIP (SET)	1	\$ 30.00	\$ 30.00
6	FRONT GRILLE CLIP	1	\$ 30.00	\$ 30.00
7	FRONT FENDER INNER COWLING CLIP	1	\$ 50.00	\$ 50.00
8	FRONT FENDER INNER GARNISH CLIP LH (SET)	1	\$ 50.00	\$ 50.00
9	FRONT PARKING SENSOR (SET)	1	\$ 220.00	\$ 220.00
10	FRONT WHEEL TYRE RH	1	\$ 380.00	\$ 380.00
11	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00
12	POWER STEERING OIL	1	\$ 60.00	\$ 60.00
13	BRAKE OIL	1	\$ 40.00	\$ 40.00

310

TOTAL \$ 1,220.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	800
3	WIRING CHECK	\$ 80.00	30
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60

5	REMOVE AND REFIX RADIATOR AND PRESSURE TEST	\$ 80.00	60
6	REFOCUS HEADLAMP BEAM	\$ 60.00	x
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	x.
9	TO PRESS FRONT WHEEL BEARING	\$ 60.00	x
11	FOUR WHEEL ALIGNMENT	\$ 120.00	x
12	RESET ABS LIGHT	\$ 350.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

1750

TOTAL \$5,100.00 1750

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,449.60
 TOTAL LABOUR COST : \$ 5,100.00
 TOTAL REPAIR COST : \$ 17,549.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE
 SERVICE ADVISOR
 IRENE
 HP : 9151 6861

Total: 6771.60
 h/s: S.H.K.

Adrian Lj
 h/s 20/09/21.
 06 Pays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4711.6
 310
 1250

 6771.60

4/s 5417.28
 5400

 88.9
 20/09/21.