

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0766/2021/GW
DATE : 14-Sep-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

2-Nov-21

OWNER'S NAME : M/S ORIENTAL SHEET PILING PTE LTD
ADDRESS : 1 COMMONWEALTH LANE
#02-03
SINGAPORE 149544
TELEPHONE : HP +65 86836633
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070171472
VEHICLE NO : **SGZ 6633 P**
MODEL CODE : Q8 3.0 TFSI
MODEL YEAR : 11/22/2018
ENGINE NO : DCB 047111
CHASSIS NO : WAUZZZF16KD006122
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE :
PLACE OF ACCIDENT :

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGZ 6633 P


S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL FRONT BUMPER WIRE HARNESS FOR HEADLIGHT AND SENSOR.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORAGNISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$ 600.00
3	TO RESPRAY FRONT BUMPER, RADIATOR GRILLE TRIM AND BOTH FRONT WHEEL ARC TRIM .	\$	2,200.00	\$ 1,450.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,952.00	\$ 2,602.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 6633 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 3,813.00	\$	3,050.40
2	FRONT BUMPER TRIM CENTER	1	\$ 406.00	\$	324.80
3	FRONT BUMPER TRIM LOWER	1	\$ 539.00	\$	430.80
4	FRONT BUMPER GRILLE LOWER CENTER	1	\$ 254.00	\$	202.80
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 292.00		
6	FRONT WHEEL ARC TRIMS LH / RH	2	\$ 1,150.00	\$	920.00
7	RADIATOR GRILLE	1	\$ 2,500.00	\$	2,000.00
8	RADIATOR GRILLE CLOSING ELEMENT CENTER	1	\$ 278.00		
9	FRONT AIR GUIDE GRILLE RH	1	\$ 437.00		
10	FRONT AIR GUIDE GRILLE DECORATIVE FRAME RH	1	\$ 333.00		
11	RADIATOR AIR GUIDE LOWER	1	\$ 42.00		
12	Added parts - see attached		\$ 1,051.00	\$	840.80
13	SUNDRIES	1	\$ 300.00	\$	9.60
TOTAL SPARE PARTS		:	\$ 11,395.00	\$	7,779.20
TOTAL LABOUR CHARGES		:	\$ 3,952.00	\$	2,602.00
GRAND TOTAL		:	\$ 15,347.00	\$	10,381.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-02/11/21



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0766/2021/GW 2-Nov-21 CHANG 1 of 1 SGZ 6633 P AUDI Q8 3.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	FRONT BUMPER TRIM - CENTER	\$ 244.50	\$	195.60
2	FRONT BUMPER UNDERRUN BAR	\$ 806.50	\$	645.20
GRAND TOTAL		\$ 1,051.00	\$	840.80

For Premium Automobiles Pte Ltd

Authorized Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT