

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST166/21/TP

Your Ref: TP claim against SKU2940H

18-Sep-21

China TaiPing Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Toyota Altis no: SDB3337B

Date of accident: 16-09-2021

Parts supply:

1 pc Bootlid <i>Dented</i>	S\$ 795.60 ✓
1 pc Bootlid emblem - Logo	61.10 ✓
1 pc Bootlid emblem - COROLLA	63.90 ✓
1 pc Bootlid emblem - ALTIS	51.90 ✓
2 pcs Bootlid lamp @\$371.75 <i>LH could</i>	743.50 371.75
2 pcs Bootlid hinges @\$182.05 <i>new</i>	364.10 +
1 pc Bootlid weatherstrip <i>cut</i>	231.35 ✓
1 pc Bootlid inner lock <i>Dented</i>	371.75 ✓
1 pc Bootlid insulator <i>new</i>	261.60 +
11 pcs Bootlid insulator clips @\$3.50 <i>new</i>	38.50 +
4 pcs Bootlid stoppers @12.50 <i>new</i>	50.00 +
1 pc Bootlid garnish	299.60 +
2 pcs Taillamps @\$412.50 <i>LH could, RH cut</i>	825.00 ✓
2 pcs Taillamp clip @\$10.00 <i>new</i>	20.00 ✓
2 pcs Taillamp lower bracket @\$78.50 <i>could</i>	157.00 110
1 pc Rear bumper <i>Distorted</i>	571.45 ✓
2 pcs Rear bumper retainers @\$90.87 <i>new</i>	181.74 ✓
2 pcs Rear bumper brackets @\$181.10 <i>Best</i>	362.20 186
8 pcs Rear bumper clips @\$3.50 <i>new</i>	28.00 ✓
1 pc Rear bumper reinforcement <i>Dented</i>	399.80 ✓
2 pcs Rear bumper sensors @\$185.30 <i>Dented</i>	370.60 ✓
2 pcs Rear bumper reflector @\$86.90 <i>new</i>	173.80 +
1 pc Rear windscreen moulding <i>new</i>	133.52 ✓
1 pc Rear L/h fender <i>Buckled</i>	1,359.60 987
2 pcs Rear fender inner trim board @\$591.60 <i>ZH sampled</i>	1,183.20 338
12 pcs Rear L/h fender inner trim board clips @\$3.50 <i>new</i>	42.00 21
1 pc Rear L/h fender mudflap <i>new</i>	98.50 ✓
1 pc Rear L/h fender air duct <i>new</i>	78.50 +
1 pc Rear L/h fender inner panel <i>new</i>	678.90 +
1 pc Fuel tank <i>new</i>	971.75 +
1 pc Fuel tank neck <i>new</i>	189.50 +
1 pc Rear end panel <i>Distorted</i>	381.90 ✓
	11,782.80

Xiao Chan

MR053REH104515368

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Toyota Altis no: SDB3337B

Date of accident: 16-09-2021

Parts supply:

Balance b/f:

- 1 pc Rear end panel garnish *Del'd*
1 pc Rear end panel garnish inner cover *new*
1 pc Spare tyre panel *Ryri*
1 pc Spare tyre panel cover *form*

SS 11,782.80
~~371.44~~ *239*
171.10 *+*
896.50 *+*
288.50 *✓*

13,510.34
Less 25%: (3,377.59)

10,132.76

7028.86
5271.64

S/Nett Items

- 1 pc Rear windscreen gum *new*
1 pc Rear no. plate with cover *new*

50

50.00 *✓*
45.00 *+*

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.

To respray affected part.

To remove & refit rear windscreen

To remove & refit rear inner trims, seat assy and roof lining to facilitate repair.

To remove & refit fuel tank.

To remove & refit rear reverse sensor.

Towing charges

To apply underseal

To remove & refit of wirings.

2710

~~1,600.00~~ *1200*
~~1,600.00~~ *1000*
~~120.00~~ *60*
~~150.00~~ *80*
~~100.00~~ *80*
60.00 *✓*
60.00 *✓*
80.00 *✓*
30.00 *✓*

SS 14,027.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian Lj
l/s 20/09/21.

09 Days.

total: 8031.64

l/s: G.HK