

BIFROST AUTO PTE LTD**8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875**

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

EstimateVehicle No: SMF6887H
Model and make: Mitsubishi Evo 10

2008

Qty Spare partsList price

1	Rear bumper	S	✓ 789.90	BRV ✓
1	Rear bumper RH side retainer	S	✓ 23.50	NECV ✓
1	Rear bumper LH side retainer	S	✓ 23.50	NECV ✓
1	RH taillamp assy	S	488.00	NDX
1	Rear windscreen glass rubber moulding	S	✓ 55.40	NECV ✓
1	Rear RH fender	S	✓ 919.30	DDV ✓
1	Rear RH fender splash shield	S	109.10	NDX
1	Rear RH fender inner trim board	S	385.00	NDX
1	Rear RH door	S	✓ 859.85	PDV ✓
1	Rear RH door frame black tape	S	✓ 31.30	NECV ✓
1	RH side rocker panel garnish	S	879.10	NDX
1	Rear RH lower arm	S	384.10	
1	Rear RH shock absorber	S	413.10	
1	Rear RH knuckle arm	S	567.50	? NDX
1	Rear RH wheel bearing	S	479.30	
1	Rear RH upper arm	S	492.00	? NDX

S 2702.75 6,599.95
 -10% S 270.28 660.00
 S 2432.48 5,939.96

Qty Spare partsSpecial Nett price

1set	Rear bumper clips	S	30.00	80.00	NECV ✓
1	Rear windscreen glass sealant	NEC	30.00	70.00	NECV ✓
1	Rear windscreen glass inner seal	S	30.00	50.00	
1	Rear RH sport rim	S	200.00	1,200.00	Cut X R
1	Rear RH tyre	S		380.00	NDX
1set	Rear RH fender inner trim board clips	S		60.00	NNX
1set	Rear RH fender joint sealant	NEC	30.00	70.00	
			320.00		

local repair 200.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.

S 800.00 1,400.00 ✓

To panel beating, cut / weld and re-align all affected panels

X

Spray painting on affected panels

S 600.00 1,200.00 ✓

Check all wiring and all lighting system

S ~~100.00~~ NNX

Apply rust coating chemical on affected panels

S ~~120.00~~ NNX

Remove and reinstall rear windscreen glass to assist repair

S 120.00 ~~220.00~~ ✓

Remove and replace RH rear fender inner trims, garnish, roof lining, seats and boards to assist repair

S ~~280.00~~ NNX

Remove and replace RH rear undercarriage parts to assist repair

S ~~350.00~~ ? NNX

Conduct and adjust wheel alignment system

S 100.00 ~~200.00~~ NNX

Remove and reinstall RH rear door inner mechanism to new door

S 80.00 100.00 ✓

1,600.00
S 11,719.96

Survey Resurvey not
20/9/2021 necessary, all
1415 hrs external damages
Trim line only

Lump sum repair
Repair day 7

Parts 2432.48
SN 320.00
Labour 1600.00
4352.48
@ 20% 870.50
3481.98

LS 3450/2

Trim line
3/11/2021

Let the Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: