

ASS. REC. BY: Marcus

REF:

CS/EP121009764/Uqf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GAB 48375

at Workshop m/s

200m

of

Insured:

SKE 87984

Policy No.

Claims No.

DM21HO01385/MT

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

206.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

534r

Vehicle: IN / OUT

Date:

Person Contacted:

Rep 66.

Veh No: GAB 48375

Yr Regn:

04/05/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA

2900L

c.c

2902

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

225726

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNCSE014297385009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxmiller

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

8

mm

L/Bal.

8/6

mm

D.O.A.

16/9/12

D.O.I.

20/9/12

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

coe unil 30-4-2024 479 6994

NO S.G. comment on 2024 with 13006

4/10/21 4/5 \$3000 confirmed with Elin (Red \$6574.12, 69%)

04/10/21@12.10pm revised to Melody by email.

Date/Time, File Pass to?

☐

: Preli. Report

1) 04/10 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) __ \$ + RS __ \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : TP

Lump Sum: \$3000

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	534R
Vehicle Details	
Vehicle No.:	GBB4837S
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2021
Vehicle Make:	KIA
Vehicle Model:	KIA 2900L 5 M/T
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	J39326459
Chassis No.:	KNCSE014297385009
Maximum Power Output:	-
Open Market Value:	\$17,791.00
Original Registration Date:	04 May 2009
First Registration Date:	04 May 2009
Transfer Count:	1
Actual ARF Paid:	\$890.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,380.00
COE Rebate Amount:	\$6,994.00
Total Rebate Amount:	\$6,994.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 20 Sep 2021

OK



Submit to insurance

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Not Authorized
20/9/21
1/5 \$3000
4 days
Telephone call up

Car Number: GBB4837S

Model : KIA 2900

Damaged Area: (Rear Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

1	Tailgate panel	20/Bent	1150	\$ 1,945.20	✓
2	Tailgate stopper rubber @ SGD 42.10	n/s torn		\$ 84.10	1 pc
3	Tailgate stopper bracket @ SGD 194.70	n/s Bent		\$ 389.40	1 pc
4	Tailgate lower "L" panel @ 145.80	NS		\$ 291.60	X
5	Tailgate hinges @ SGD 48.70	NS		\$ 97.40	X
6	Tailgate side lock @ SGD 68.70	n/s		\$ 137.40	X
7	Tailgate safety lock @ SGD 142.70	n/s		\$ 285.40	X
8	Tailgate lower member	20/Bent		\$ 786.10	✓
9	Taillamp @ SGD 497.20	n/s one	220	\$ 994.40	1 pc
10	Taillamp bracket @ SGD 196.50	NS		\$ 393.00	X
11	Rear step panel	n/s		\$ 486.20	X
12	Side gate LH	n/s		\$ 986.50	X

Parts : \$

Less Parts 10% : \$

Total Parts : \$

Special Net Items :

Tailgate lower member sealant	11	\$ 80.00	X
Tailgate sticker (70km/h)	11	\$ 35.00	10 S/N
Tailgate sticker (13pax)	11	\$ 35.00	10 S/N
Rear number plate	5 n/s	\$ 35.00	✓ S/N
Reverse sensor with module	n/s	\$ 280.00	X

Total S/N Parts : \$

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,200.00	800
To Putty, Spray Paint on Affected Accident Areas	\$ 1,200.00	700
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Rear Tailgate Components Trim & Attachment	11 \$ 150.00	X
To Re-position & Align Reverse Sensor	11 \$ 120.00	X
To Rust Proof Affected Areas	\$ 200.00	60

Total Labour : \$

TOTAL PARTS :

TOTAL SPECIAL NET ITEM

TOTAL LABOUR :

TOTAL REPAIR COST :

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: