

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : SLQ 8822 K

Model : Toyota C-HR Hybrid 1.8

Year : 2017

Chassis No : ZYX102019672

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 1,124.50	\$ 855.10 1,124.50
2	Rear bumper lower lid	1	\$ 465.00	\$ 397.60 465.00
3	Rear bumper lower lid centre garnish	1	\$ 68.00	\$ 68.00
4	Rear bumper side retainer	2	\$ 84.00	\$ ✓ 168.00
5	Rear bumper reinforcement	1	\$ 578.90	\$ 393.20 578.90
6	Rear bumper inner S-side bracket	2	\$ 104.20	\$ 208.40
7	Rear bumper tow cover	1	\$ 35.00	\$ 35.00
8	Rear bumper reflector LH	1	\$ 218.00	\$ 118.00 218.00
9	Rear bumper reflector garnish LH	1	\$ 135.00	\$ ✓ 135.00
10	Rear bumper reverse sensor	2	\$ 185.00	\$ 200.00 740.00
11	Rear end panel	1	\$ 789.10	\$ 789.10
12	Rear end panel top garnish	1	\$ 285.70	\$ 285.70
13	Rear fender inner trim board LH	1	\$ 987.90	\$ 987.90
14	Rear fender arch garnish LH	1	\$ 295.00	\$ 201.35 295.00
15	Taillamp LH	1	\$ 982.20	\$ 566.10 982.20
16	Taillamp lower bracket LH	1	\$ 78.00	\$ ✓ 78.00
Parts Sub Total :				\$ 3112.35 7,158.70
Discount :				\$ 778.09 1,789.68
PARTS TOTAL :				\$ 5,369.03

25%

2334.26

2017

BR✓
BR✓
NDX
NECV
DD✓
NSX
NDX
BR✓
BR✓
SC✓
DDXR
NDX
NDX
BR✓
BR✓
BR✓

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Rear bumper clips	1	\$ 50.00	\$ 50.00 30.00
3	Rear bumper lower lid clips	1	\$ 50.00	\$ 50.00 20.00
4	Rear bumper reflector garnish clips	1	\$ 50.00	\$ 50.00
5	Rear bumper reverse sensor seal	2	\$ 48.00	\$ 96.00 96.00
6	Rear end panel sealant	1	\$ 100.00	\$ 100.00
7	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
8	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00
9	Rear fender arch garnish clips	1	\$ 50.00	\$ 50.00 30.00
10	Taillamp clips	1	\$ 50.00	\$ 50.00 20.00
11	Taillamp seal	1	\$ 60.00	\$ 60.00
SPECIAL NETT TOTAL :				\$ 782.00

196.00

Nos.	LABOUR	S\$
1	R&R rear bumper reverse sensor	\$ 100.00 60.00
2	Check wiring	\$ 100.00 20.00
3	Upholstery	\$ 300.00
4	Diagnostic reset fault code	\$ 300.00
5	Panel beating	\$ 1,200.00 600.00
6	Rust proofing	\$ 200.00
7	Spray painting	\$ 1,200.00 400.00
LABOUR TOTAL :		\$ 3,400.00

1080.00

PARTS TOTAL : \$ 5,369.03
SPECIAL NETT TOTAL : \$ 782.00
LABOUR TOTAL : \$ 3,400.00
GRAND TOTAL : \$ 9,551.03

Survey 20/9/2021
Resurvey 21/9/2021
1620 hrs
1200 hrs
Talin
Talin
lin
lin

Part by Part repair
Repair days 4

Parts 2334.26
SN 196.00
Labour 1080.00

3610.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Part by Part cor \$ 3600.00

Talin lin
28/9/2021