

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 21.29071 Date: 05th Oct 2021

Our Ref: CS3/ASM21004737/Eqce2-1

M/s Axa Insurance Pte Ltd

C/o: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMY 4956E INSURED VEHICLE: SKV 5699E ACCIDENT DATE: 17/03/2021

11001221(1 21112(1),00,2021

We thank you for your instruction on 20/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMY 4956E from M/s Automax Survey.
- b) Singapore Accident Statement of Vehicle SMY 4956E and SKV 5699E.
- c) Final Repair Bill of SMY 4956E from M/s Hup Ley Huat Motor Spray Painting Services.
- d) Colour damaged vehicle photographs of SMY 4956E.

Pre-Repair Inspection Date: 19/04/2021 at M/s Hup Ley Huat Motor Spray Painting Services, Blk 1 Kaki Bukit Ave 6, #01-35 Autobay, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMY 4956E

Make & Model : Toyota Sienta Hybrid 7-Seater 1.5G CVT

Year of Registration : 2021

Chassis Number : NHP1707198130

Engine Capacity : 1496 cc

- 2. We recommend that the repairs of the entire damage require about ______ to ____ working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.