



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21004737/Eqc-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM21004737/E~~
Date: ~~11/01/2021~~ 20/09/2021
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKV 5699E	Veh. Inspected	SMY 4956E
Policy No.	21.29071	Coverage (\$)	0.00
Claim No.	S1M03604	Excess (\$)	0.00
Assign From	Chu Xichi Eugene	Assign Date	11/01/2021 20/09/2021

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/03/2021	Inspection Date	04/04/2020 19/04/2021
Survey held at	MR TAN: 9677 3832		
Repairer	HUP LEY HUAT MOTOR SPRAY PAINTING SVS		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.