

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 21 Sep 2021

Preliminary Advice

Insured Vehicle No	: SKZ265K	Accident Date	: 17/09/2021
TP Vehicle No	: SMW2350B	Assignment Date	: 20/09/2021
Make	: MERCEDES-BENZ GLA180 URBAN (R18 LED)	Est. Duration of Repair	: 7
Date of Inspection	: 20/9/21		
Inspection At	: VIN'S MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,086.00
Revised Amount	:S\$	10,691.30
Check Items (Estimated)	:S\$	3,070.00
Total	:S\$	13,761.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Some of the parts pending for parts prices

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .