



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 60904
ESTIMATE COST OF REPAIRS

PORSCHE

CHINA TAIPING INSURANCE (SINGAPORE)		NAME :		WIP :		21921
3 Anson Road		ADDRESS :		EXCESS :		
#16-00 Springleaf Tower				DATE:		16-Sep-21
Singapore 079909		TEL :				
ATTN. :		MOTOR CLAIMS				
FAX :						
VEH NO :	SJP9088K	DATE IN :		CONTACT PERSON :		JOBI 63310682
CHASSIS NO :	WP0ZZZ97JL117689	MILEAGE :		TYPE OF CLAIM :		OWN DAMAGE
MODEL :	Panamera	DATE REG.:	7-Nov-18	POLICY NO. :		

NATURE OF WORKS

S/NO	Parts Description					
	QTY			1ST	SUPP	REVISED
1	FRONT BUMPER	1	P971-898-010- -			\$ 2,237.60
2	FRONT GRILLE CENTER	1	P971-807-683-B -OK1			\$ 308.50
3	FRONT GRILLE LH	1	P971-807-681- -OK1			\$ 129.00
4	FRONT GRILLE LH OUTER TRIM	1	P971-807-485- -OK1			\$ 99.30
5	FRONT GRILLE DISC SUPPORT LH	1	P971-807-985- -OK1			\$ 94.50
6	FRONT GRILLE LH DISC	1	P971-807-877- -OK1			\$ 127.70
7	HOUSING FOR CAMERA	1	P971-807-762- -OK1			\$ 43.00
8	SUPPORT BRACKET FOR CAMERA	1	P971-807-997- -			\$ 40.20
9	SENSOR	6	P5Q0-919-275-B -G2X			\$ 1,511.40
10	SENSOR GASKET	6	P5Q0-919-133- -9B9			\$ 18.60
11	NUMBER PLATE BRACKET	1	P971-807-999- -OK1			\$ 85.00
12	HEADLIGHT BRACKET LH	1	P971-807-347- -			\$ 85.80
13	FRONT BUMPER RETAINER LH	1	P971-807-283- -			\$ 38.80
14	FIXING DEVICE	2	P971-807-180- -			\$ 27.40
15	FRONT BUMPER REINFORCEMENT	1	P971-805-241-E -			\$ 1,099.90
16	FRONT BUMPER SPONGE	1	P971-807-550- -			\$ 83.90
17	ADDITIONAL HEADLAMP LH	1	P971-953-041-H -			\$ 757.30
	SUPPLEMENTARY PART					
1	DISC CARRIER BLACK MAT cra	1	P971-121-257-B -OK1			\$ 854.20
2	AIR DUCT cra	1	P971-121-710-E -			\$ 414.90
3	ANTENNA (NEC) cra	2	P971-035-510-E -			\$ 449.20
TOTAL PARTS						\$ 5,508.70
TOTAL PARTS COST						\$ 5,508.70

	Labour Description					
1	TO REMOVE /REPLACE FRONT BUMPER, REINFORCEMENT & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.					
2	TO RESPRAY FRONT BUMPER .					
3	TO SUPPLY FRONT LICENCE PLATE WITH CASING					
4	TO TRANSFER THE FRONT SENSORS.					