

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM21009774/Avce2	
	8 SHENTON WAY AXA TOWERSING		Date:	11/11/2021	
	ATTN: TEO KITTY		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 699J	Veh. Inspected	GX 8069R	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S1M03I6T	Excess (\$)	0.00	
	Assign From	TEO KITTY	Assign Date	20/09/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA LITEACE	c.c	2184	
	Engine No.	HIDDEN	Year of Reg.	2004	
	Chassis No.	CR425010555	Colour	SILVER	
	Odometer	238387 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	165 R13C	YOKOHAMA	6 mm	
	L/H Front Tyre	165 R13C	YOKOHAMA	6 mm	
	R/H Rear Tyre	165 R13C	YOKOHAMA	6 mm	
	L/H Rear Tyre	165 R13C	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/09/2021	Inspection Date	20/09/2021	
	Survey held at	at HIAP HONG MOTOR REPAIR			
		2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921			
5a.	Remarks				
	N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. S)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				