

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009776/EGS3Q2
Date: 08/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SHB5000L	Insured Vehicle No :	SLN3785H
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004115

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5000L		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2C15307
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU503080425
Colour:	Yellow	Odometer:	251726 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 4 mm	Rear Left Side:	Sailun 4 mm
Front Right Side:	Sailun 4 mm	Rear Right Side:	Sailun 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,635.78	2,985.10	6,650.68	69.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	2,070.00	3,780.00	64.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,485.78	5,055.10	10,430.68	67.36
Approved Total (Overridden) (S\$)		4,050.00		

(S\$)	15,485.78	4,050.00	11,435.78	73.85
+ GST 7.00/7.00% (S\$)	1,084.00	283.50	800.50	73.85
Nett Amount (S\$)	16,569.78	4,333.50	12,236.28	73.85
+ Car Rental (10.0 x S\$118.20/day) (S\$)		1,182.00		
+ Loss of Earnings (10.0 x S\$40.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,922.95		

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 20/09/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Ding Automotive Pte Ltd (SIN MING)
 BLK 10 #01-20 SIN MING, IND EST SEC C
 Singapore 575645

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB5000L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR PANEL	Dented	1,635.99 FL	*1,300.97 FL
2	1		*FRONT LH BLACK OUT TAPE NO.1	Necessary	13.30 FL	*13.30 FL
3	1		*FRONT LH BLACK OUT TAPE NO.2	Necessary	43.50 FL	*43.50 FL
4	1		*FRONT LH BLACK OUT TAPE NO.3	Necessary	26.30 FL	*26.30 FL
5	1		*FRONT LH DOOR WINDOW REGULATOR SUB-ASSY	Not Necessary	285.21 FL	*- FL
6	1		*FRONT LH DOOR WINDOW REGULATOR MOTOR	Not Necessary	926.00 FL	*- FL
7	1		*FRONT LH DOOR REAR LOWER FRAME SUB-ASSY	Not Necessary	93.69 FL	*- FL
8	1		*FRONT LH OUTER DOOR HANDLE	Not Necessary	141.76 FL	*- FL
9	1		*FRONT LH OUTER DOOR HANDLE COVER	Not Necessary	17.90 FL	*- FL
10	1		*FRONT LH OUTER DOOR HANDLE FRAME SUB-ASSY	Not Necessary	193.50 FL	*- FL
11	1		*FRONT LH DOOR LOCK ASSY	Not Necessary	561.90 FL	*- FL
12	1		*REAR LH DOOR PANEL	Dented	1,635.90 FL	*1,294.90 FL
13	1		*REAR LH BLACK OUT TAPE NO.1	Necessary	21.90 FL	*21.90 FL
14	1		*REAR LH BLACK OUT TAPE NO.2	Necessary	34.90 FL	*34.90 FL
15	1		*REAR LH BLACK OUT TAPE NO.3	Necessary	15.40 FL	*15.40 FL
16	1		*REAR LH DOOR LOCK ASSY	Not Necessary	561.90 FL	*- FL
17	1		*REAR LH DOOR WINDOW REGULATOR SUB-ASSY	Not Necessary	285.21 FL	*- FL
18	1		*REAR LH DOOR WINDOW REGULATOR MOTOR	Not Necessary	926.00 FL	*- FL
19	1		*REAR LH UPPER DOOR HINGE	Not Necessary	98.90 FL	*- FL
20	1		*REAR LH LOWER DOOR HINGE	Not Necessary	87.10 FL	*- FL
21	1		*REAR LH DOOR WEATHERSTRIP NO.3	Torn	36.20 FL	*36.20 FL
22	1		*REAR LH DOOR WINDOW DIVISION BAR SUB-ASSY	Not Necessary	112.30 FL	*- FL
23	1		*REAR LH DOOR CHECK	Not Necessary	183.80 FL	*- FL
24	1		*REAR LH DOOR WEATHERSTRIP	Not Necessary	178.85 FL	*- FL
25	1		*SIDE SKIRT LH	Repair	675.47 FL	*- FL
26	1		*REAR LH QUARTER PANEL	Dented	899.43 FL	*899.43 FL
27	1		*REAR LH FENDER LINE	Not Necessary	139.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR LH WHEEL RIM	Repair	1,555.60 FL	*- FL
29	1		*SET REAR BUMPER CLIP	Not Necessary	60.00 FS	*- FS
30	1		*SET REAR FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
31	1		*REAR TYRE 195/65/15	Not Necessary	200.00 FS	*- FS
32	2		*REAR QUARTER PANEL SEALANT	Necessary	170.00 FS	*30.00 FS
33	1		*SET SIDE SKIRT CLIP	Not Necessary	65.00 FS	*- FS
34	1		*REAR DOOR COMFORT DELGRO STICKER	Necessary	140.00 FS	*50.00 FS
35	1		*REAR DOOR GOOGLE PLAY STORE APP STORE STICKER	Necessary	140.00 FS	*30.00 FS
36	1		*FRONT DOOR COMFORT DELGRO STICKER	Necessary	140.00 FS	*80.00 FS
37	1		*SET DOOR MOULDING CLIP	Not Necessary	55.00 FS	*- FS
38	1		*SET DOOR TRIM BOARD CLIP	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,482.71	3,906.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,846.93	921.70
Total Parts (\$\$)	9,635.78	2,985.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	New	2,200.00	1,000.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	200.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	New	350.00	0.00
4	TO DIAGNOSTIC ,CHECK WIRING AND LIGHTING SYSTEM AD CLEAR FAULT CODE	New	270.00	30.00
5	TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	New	240.00	100.00
6	TO REAPPLY SEAL JOINT ON WELDING AFFECTED AREAS	New	180.00	0.00
7	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	160.00	60.00
8	TO RESPRAY REAR OUTER QUARTER WHEEL HOUSE PANEL	New	250.00	200.00
9	TO RESPRAY SIDE SKIRT LH	New	250.00	200.00
10	TO RESPRAY ROCKER PANEL	New	250.00	0.00
11	TO RESPRAY REAR DOOR PANEL	New	250.00	200.00
12	TO RESPRAY REAR WHEEL RIM	New	250.00	50.00
13	TO RESPRAY FRONT DOOR PANEL	New	250.00	200.00
14	TO RESPRAY FRONT SIDE MIRROR	New	250.00	0.00
15	TO RESPRAY REAR QUARTER PANEL	New	250.00	0.00
16	TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE	New	250.00	0.00
Gross Labour Cost (\$\$)			5,850.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >