

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

20/09/2021 11:40

JOB-NO: 50113633

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB5000L

TRANS: AUTO

CHASSIS: JTDKB3FU503080425

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2C15307

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	2,200.00	0.00	2,200.00	1000	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	200.00	0.00	200.00	30	Y	
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	1.00	350.00	0.00	350.00	X	Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	270.00	0.00	270.00	30	Y	
5 TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	240.00	0.00	240.00	100	Y	
6 TO REAPPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	180.00	0.00	180.00	X	Y	
7 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	160.00	0.00	160.00	60	Y	
8 TO RESPRAY REAR OUTER QUARTER WHEEL HOUSE PANEL	1.00	250.00	0.00	250.00	200	Y	
9 TO RESPRAY SIDE SKIRT LH	1.00	250.00	0.00	250.00	100	Y	
10 TO RESPRAY ROCKER PANEL	1.00	250.00	0.00	250.00	X	Y	
11 TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	
12 TO RESPRAY REAR WHEEL RIM	1.00	250.00	0.00	250.00	50	Y	
13 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	
14 TO RESPRAY FRONT SIDE MIRROR	1.00	250.00	0.00	250.00	X	Y	
15 TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	X	Y	
16 TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE	1.00	250.00	0.00	250.00	X	Y	
TOTAL:		5,850.00	0.00	5,850.00			

MATERIALS

1 FRONT LH DOOR PANEL - DO	1.00	1,635.99	409.00	1,226.99	L	1300.97	
2 FRONT LH BLACK OUT TAPE NO.1 - REC	1.00	13.30	3.33	9.97	L	Y	
3 FRONT LH BLACK OUT TAPE NO.2 - REC	1.00	43.50	10.88	32.62	L	Y	
4 FRONT LH BLACK OUT TAPE NO.3 - REC	1.00	26.30	6.58	19.72	L	Y	
5 FRONT LH DOOR WINDOW REGULATOR SUB-ASSY ? X m	1.00	285.21	71.30	213.91	L	Y	
6 FRONT LH DOOR WINDOW REGULATOR MOTOR ? X m	1.00	926.00	231.50	694.50	L	Y	
7 FRONT LH DOOR REAR LOWER FRAME SUB-ASSY ? X m	1.00	93.69	23.42	70.27	L	Y	
8 FRONT LH OUTER DOOR HANDLE X m	1.00	141.76	35.44	106.32	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
9 FRONT LH OUTER DOOR HANDLE COVER X	1.00 nn	17.90	4.48	13.42	L	Y	
10 FRONT LH OUTER DOOR HANDLE FRAME X	1.00 nn	193.50	48.38	145.12	L	Y	
SUB-ASSY							
11 FRONT LH DOOR LOCK ASSY ? X nn	1.00	561.90	140.48	421.42	L	Y	
12 REAR LH DOOR PANEL - DD	1.00	1,635.99	409.00	1,226.99	L	Y	1294.90
13 REAR LH BLACK OUT TAPE NO.1 - nec	1.00	21.90	5.48	16.42	L	Y	
14 REAR LH BLACK OUT TAPE NO.2 - nec	1.00	34.90	8.73	26.17	L	Y	
15 REAR LH BLACK OUT TAPE NO.3 - nec	1.00	15.40	3.85	11.55	L	Y	
16 REAR LH DOOR LOCK ASSY ? X nn	1.00	561.90	140.48	421.42	L	Y	
17 REAR LH DOOR WINDOW REGULATOR ? X nn	1.00	285.21	71.30	213.91	L	Y	
SUB-ASSY							
18 REAR LH DOOR WINDOW REGULATOR ? X nn	1.00	926.00	231.50	694.50	L	Y	
MOTOR							
19 REAR LH UPPER DOOR HINGE X nn	1.00	98.90	24.73	74.17	L	Y	
20 REAR LH LOWER DOOR HINGE X nn	1.00	87.10	21.78	65.32	L	Y	
21 REAR LH DOOR WEATHERSTRIP NO.3 - nn	1.00	36.20	9.05	27.15	L	Y	
22 REAR LH DOOR WINDOW DIVISION BAR ? X nn	1.00	112.30	28.08	84.22	L	Y	
SUB-ASSY							
23 REAR LH DOOR CHECK X nn	1.00	183.80	45.95	137.85	L	Y	
24 REAR LH DOOR WEATHERSTRIP X nn	1.00	178.85	44.71	134.14	L	Y	
25 SIDE SKIRT LH X R	1.00	675.47	168.87	506.60	L	Y	
26 REAR LH QUARTER PANEL - DD	1.00	899.43	224.86	674.57	L	Y	
27 REAR LH FENDER LINER X nn	1.00	139.80	34.95	104.85	L	Y	
28 REAR LH WHEEL RIM X R	1.00	1,555.60	388.90	1,166.70	L	Y	
29 REAR BUMPER CLIP SET X nn	1.00	60.00	0.00	60.00	S	Y	
30 REAR FENDER LINER CLIP SET X nn	1.00	65.00	0.00	65.00	S	Y	
31 REAR TYRE 195/65/15 X nn	1.00	200.00	0.00	200.00	S	Y	
32 REAR QUARTER PANEL SEALANT - nec	2.00	170.00	0.00	170.00	S	Y	
33 SIDE SKIRT CLIP SET X nn	1.00	65.00	0.00	65.00	S	Y	
34 REAR DOOR "COMFORT DELGRO" STICKER -	1.00	140.00	0.00	140.00	S	Y	
35 REAR DOOR "GOOGLE PLAY STORE" "APP STORE" STICKER -	1.00	140.00	0.00	140.00	S	Y	
36 FRONT DOOR "COMFORT DELGRO" STICKER -	1.00	140.00	0.00	140.00	S	Y	
37 DOOR MOULDING CLIP SET X nn	1.00	55.00	0.00	55.00	S	Y	
38 DOOR TRIM BOARD CLIP SET - nec	1.00	60.00	0.00	60.00	S	Y	
TOTAL:		12,482.80	847.01	9,635.79			
TOTAL PARTS & LABOUR :		18,332.80	2,847.01	15,485.79			

EXCESS/LOADING:\$S 0.00

No. Of Day:

8 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$S

DATE OF SURVEY: 20/09/21, 11.00 am

SURVEYED BY:

Steve (LKK)

CONTACT NO:

L/S, Resurvey After Spray

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

L-3686.80
-25%
2765.10

220

P-2765.10

N-220

L-2070

5055.10

L/S-4044.08

= 4050