



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206117(R1)

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 03/10/2022
Reference CC6/CTI21009777/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBL 2109X
Insured Veh. GBC 9827H
Claim No. SNM21D205281/C02
Policy No. DMCVSNW00003882100
Accident Date 15/09/2021
Inspection Date 20/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21009777/Uea3q2 Date: 03/10/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 9827H	Veh. Inspected	GBL 2109X	
Policy No.	DMCVSNW00003882100	Coverage (\$)	0.00	
Claim No.	SNM21D205281/C02	Excess (\$)	0.00	
Assign From		Assign Date	20/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JN1YAAM20Z0001370	Colour	WHITE	
Odometer	7212 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/80 R14	TOYO	8 mm	
L/H Front Tyre	165/80 R14	TOYO	8 mm	
R/H Rear Tyre	165/80 R14	TOYO	8 mm	
L/H Rear Tyre	165/80 R14	TOYO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/09/2021	Inspection Date	20/09/2021	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 2109X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	624.80	624.80
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER SPONGE	TORN	122.00	122.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	285.30	-
1	TAIL LAMP (N/S)	SCRATCHED	252.10	252.10
1	TAILGATE	TO REPAIR SEE LABOUR	1,835.20	-
	LESS 10% DISCOUNT		-	-102.89
			3,149.40	926.01
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	TAILGATE '70KM/H' STICKER (SN)	NECESSARY	15.00	10.00
1	TAILGATE '6 PAX' STICKER (SN)	NECESSARY	15.00	10.00
1	'CORPORATE' ADVERTISEMENT & ARTWORK (SN)	NECESSARY	150.00	100.00
			430.00	320.00
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION .		30.00	20.00
	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR .		50.00	40.00
	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REAIR OF REAR END PANEL AND TAILGATE.		500.00	400.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		500.00	300.00
			1,080.00	760.00
	GRAND TOTAL		4,659.40	2,006.01



RECOMMENDED COST OF REPAIRS			2,006.01
-----------------------------	--	--	-----------------

Report Ref No. CC6/CTI21009777/Uea3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 2109X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 2109X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 2109X

RE-INSPECTION

