

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Sep-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8081 H

1 pc	n/s mirorr Assy	\$	590.00/mis
1 pc	Front n/s door	\$	796.00xr
1 pc	Front n/s door outer handle	\$	44.00/mis
1 pc	Front n/s door handle outer cover (Small)	\$	10.00/nec
1 pc	Front n/s door handle base Assy	\$	39.00/nec
		\$	1,479.00
	Less 10%	\$	147.90
		\$	1,331.10

S/NETT

1 set	o/s door stickers	\$	100.00/nec
	Sundry	\$	50.00xsuc
▷	To dismantle and refit the inner componnet of front n/s door into new shell door	\$	150.00 60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc	\$	600.00 450
	To putty and spray painting on front n/s fender, front n/s door, rear n/s door, n/s mirror cover	\$	700.00 600
	To apply rustproofing on repaired panels	\$	120.00 30
		\$	3,051.10

F. \$1450

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Theran @ Lkh auto-loan
82235769
L/S ~~for~~ paint photos
20/9/21 1400 30
4 days wp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: