

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719

E-mail : xinyaauto@gmail.com

Tel: 6270 3481 Fax: 6278 7522

Date : 17/09/2021

Address : CONTINENTAL EQUIPMENT PTE LTD
BLK 17A JOO YEE ROAD

SINGAPORE 619202

Reference : TP 1295/09/21
Vehicle No : GBA 9488M
Make/Model : SUZUKI EVERY
Insurance Co. : MSIG

RE : QUOTATION TO GBA 9488M FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) REAR BUMPER / OO	1	\$ 596.75
2) REAR BUMPER RETAINER / BR	1	\$ 20.15
3) REAR BUMPER LAMP (RH) - BR	1	\$ 170.65
4) TAIL DOOR / OO	1	\$ 868.95
5) TAIL DOOR RUBBER / TM ?	1	\$ 124.50
6) TAIL DOOR LOCK / R	1	\$ 181.10
7) TAIL DOOR "SUZUKI" LOGO / - 11K	1	\$ 23.00
8) REAR WINDSCREEN GLASS / - BR	1	\$ 458.05
9) REAR WINDSCREEN CLIPS / - 11K	4	\$ 20.00

LIST PRICE TOTAL \$ 2,463.15
LESS DISCOUNT 25% \$ 615.79
LIST PRICE TOTAL AFTER LESS \$ 1,847.36

10) TAIL DOOR STICKER "70KM" / - 11K	1	\$ 10.00
11) TAIL DOOR STICKER "5 PAX" / - 11K	1	\$ 10.00
12) WINDSCREEN SEALANT / - 11K	1	\$ 60.00 40

NETT PRICE TOTAL \$80.00

TOTAL PARTS COST \$1,927.36

LABOUR AND MISCELLANEOUS CHARGES

1) TO REMOVE & REPLACE REAR BUMPER, TAILGATE, ENFORCEMENT AND TO PANEL BEAT END PANEL & ALIGN.	\$ 800.00 (4 DAYS)	400
2) TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE INNER & OUTER, END PANEL AND OTHER AFFECTED AREA	\$ 800.00 (4 PANELS)	400

- 3) TO CHECK & RECTIFY WIRING. \$ 80.00 30
- 4) TO TRANSFER DOOR MECHANISIM TO NEW DOOR \$ 280.00 50
- 5) TO FIT NEW WINDSCREEN GLASS & CHECK FOR WATER TIGHT \$ 120.00 ✓

LABOUR TOTAL

\$ 2,080.00

TOTAL ESTIMATED REPAIR COST

\$ 4,007.36

Steve CLKK
20/9/21, 4:30pm

WML AL
L/S
M AL S
4 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: