

# XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719  
 E-mail : xinyaauto@gmail.com  
 Tel: 6270 3481 Fax: 6278 7522

Date : 17/09/2021

Address : CONTINENTAL EQUIPMENT PTE LTD  
 BLK 17A JOO YEE ROAD  
 SINGAPORE 619202

Reference : TP 1295/09/21  
 Vehicle No : GBA 9488M  
 Make/Model : SUZUKI EVERY  
 Insurance Co. : MSIG

## RE : QUOTATION TO GBA 9488M FOR THIRD PARTY CLAIMS.

PARTS REQUIRED		QTY	AMT \$
1)	REAR BUMPER / <i>DD</i>	1	\$ 596.75 <i>540/-</i>
2)	REAR BUMPER RETAINER / <i>BR</i>	1	\$ 20.15
3)	REAR BUMPER LAMP / <i>(RH) - BR</i>	1	\$ 170.65
4)	TAIL DOOR / <i>DD</i>	1	\$ 868.95
5)	TAIL DOOR RUBBER / <i>TN ? - BT</i>	1	\$ 124.50
6)	TAIL DOOR LOCK / <i>BR</i>	1	\$ 181.10
7)	TAIL DOOR "SUZUKI" LOGO / <i>BR</i>	1	\$ 23.00
8)	REAR WINDSCREEN GLASS / <i>BR</i>	1	\$ 458.05
9)	REAR WINDSCREEN CLIPS / <i>BR</i>	4	\$ 20.00
LIST PRICE TOTAL <i>20</i>			\$ 2,463.15
LESS DISCOUNT <i>25%</i>			\$ 615.79
LIST PRICE TOTAL AFTER LESS			\$ 1,847.36
10)	TAIL DOOR STICKER "70KM" / <i>BR</i>	1	\$ 10.00
11)	TAIL DOOR STICKER "5 PAX" / <i>BR</i>	1	\$ 10.00
12)	WINDSCREEN SEALANT / <i>BR</i>	1	\$ 60.00 <i>40/-</i>
NETT PRICE TOTAL <i>60/-</i>			\$ 80.00
TOTAL PARTS COST			<b>\$1,927.36</b>

*2406.40*  
*-20%*  
*1925.12*

## LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, TAILGATE, ENFORCEMENT AND TO PANEL BEAT END PANEL & ALIGN.	\$ 800.00 (4 DAYS)	<i>400</i>
2)	TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE INNER & OUTER, END PANEL AND OTHER AFFECTED AREA.	\$ 800.00 (4 PANELS)	<i>400</i>

- 3) TO CHECK & RECTIFY WIRING. \$ 80.00 30
- 4) TO TRANSFER DOOR MECHANISIM TO NEW DOOR \$ 280.00 50
- 5) TO FIT NEW WINDSCREEN GLASS & CHECK FOR WATER TIGHT \$ 120.00 ✓

1000 ✓

**\$ 2,080.00**

**LABOUR TOTAL**

**\$ 4,007.36**

**TOTAL ESTIMATED REPAIR COST**

4381.80

Steve (LKK)  
20/9/21, 4:30pm

W/L AL  
L/S  
4 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer  
Signature:  
Date:

P- 1925.12  
M- 60  
L- 1000  
SUPP - 251.28  
3236.40  
L/S - 2589.12  
= 2600

# XINYA AUTO SERVICES PTE LTD

BLK 1002 BUKIT MERAH LANE 3, UNIT # 01 -75, SINGAPORE 159719  
E-mail : xinyaauto@gmail.com

Date : 21/09/2021

Steve (LKK) 24/9/21

Address : CONTINENTAL EQUIPMENT PTE LTD  
BLK 17A JOO YEE ROAD  
SINGAPORE 619202

Reference : TP 1295/09/21  
Vehicle No : GBA 9488M  
Make/Model : SUZUKI EVERY  
Insurance Co. : MSIG

## RE : QUOTATION TO GBA 9488M FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>COST</u>	<u>AMT \$</u>
1) REAR TAILGATE WIPER MOTOR	1 / RT / Jomard		\$314.10

LIST PRICE TOTAL	\$	314.10
LESS DISCOUNT 20%	\$	62.82
LIST PRICE TOTAL AFTER LESS	\$	251.28

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST \$251.28

### LABOUR AND MISCELLANEOUS CHARGES

LABOUR TOTAL \$ -

TOTAL ESTIMATED REPAIR COST \$ 251.28