

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 22 TAMPINES ST 92 (S  
528876)

Jonathan Lim  
CLAIM DEPARTMENT  
DID : 66547606  
FAX : 66547540

Date : 20/09/2021  
To : LKK AUTO CONSULTANTS PTE LTD

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd  
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MHCVL000057  
Vehicle No : GBG-2465-1  
Accident Date : 11/09/2021  
Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	FRONT BUMPER / <i>Cut</i>	571.90	✓
1	FRONT RH BUMPER RETAINER <i>x NN</i>	181.90	
10	FRONT BUMPER CLIP <i>clip</i>	50.00	✓
1	FRONT RH SIDE STEP <i>clip</i>	67.50	✓
1	FRONT RH MUFLAP <i>Cut</i>	105.50	✓
1	RH "A" PILLAR <i>Repair</i> X		RESTORE
1	FRONT DOOR RH <i>Repair</i> X	1,071.40	
1	FRONT RH FENDER <i>Repair</i> X		RESTORE
1	FRONT RH UPPER ARM <i>x NN</i>	377.90	

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Date : 20/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT RH LOWER ARM <del>X</del> NN	228.40	
1	FRONT RH ABSORBER /	140.20	✓
2	FRONT RH ABSORBER RUBBER STOPPER / SAT.	40.00	✓
1	FRONT RH ABSORBER BRACKET X NN RESTORE		
1	FRONT RH KUNCKLE ARM <del>X</del> NN	315.20	
1	FRONT RH WHEEL HUB <del>X</del> NN	453.00	
1	FRONT RH WHEEL BEARING / Im	231.00	✓
1	TIE ROD END RH <del>X</del> NN	142.00	
1	TIE ROD RH <del>X</del> NN	98.00	
1	FRONT RH ABS SENSOR / OR	397.00	✓

Date: 10/06/2021  
 To: **LEK AUTO CONSULTANTS PTE LTD**  
 Attn: Motor Claims Department

## ESTIMATION

FAX:

From: ETHOZ Group Ltd  
 50 BRIDGE ROAD #04-01 SINGAPORE PTE LTD

Certificate No: D17MCHV1000007      Accident Date: 11-06-2021  
 Vehicle No: C8C 2805 Y      Make & Model: NISSAN NV150 PANEL VAN 1.7 DIESEL C 150

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	Excess	REPAIRER AMT (\$)	REVEYOR APP
		0.00	Add Excess	0.00
1	FRONT RH DR A/L CALIPER HOUSING <i>cut</i>		47.50	✓
1	WHITE RIM COVER <i>cut</i>		161.50	✓
1	FRONT RH TYRE RIMS INCH <i>cut</i>		27.50	✓
	<b>Sub Total</b>		<b>497.80</b>	
	<b>Discount 10% On Parts</b>		<b>(49.78)</b>	
<b>Special Note Here</b>				
1	COMPANY DEL AI STRUCKER <i>del</i>		20.00	✓
1	TYRE WHEEL <i>from</i>		200.00	90
1	TOWING CHARGES FROM ACCIDENT AREA INTO W. 500.00 <i>- Invoice</i>		150.00	110

Date : 20/09/2021  
 To : LKK AUTO CONSULTANTS PTE LTD  
 Attn : Motor Claim Department

## ESTIMATION

FAX :

Owner : ETHOZ Group Ltd  
 : SOMPO INSURANCE SINGAPORE PTE. LTD.  
 Certificate No : D17MTHCVE000057      Accident Date : 11/09/2021  
 Vehicle No : GBG-2465-T      Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00      Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	<b>Sub Total</b>	<b>370.00</b>	
	<b>Labour &amp; Misc</b>		
	LABOUR TO FACILITATE REPAIR	800.00	600 ✓
	TO REMOVE & INSTALL RHF UNDERCARRIAGE PARTS	200.00	150 ✓
	TO REMOVE & INSTALL RHF RIM INCLUDING TYRE BALANCING	20.00	— ✓
100	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH & RECTIFY CHASSIS TO RECOMMENDED SPECIFICATION	1,800.00	<del>180</del> - photo.
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	80.00	60
	TO RESET & RE-PROGRAM WARNING LIGHT ON	120.00	<del>7</del> 80

Date : 20/09/2021  
 To : **LKK AUTO CONSULTANTS PTE LTD**  
 Attn : **Motor Claim Department**

## ESTIMATION

FAX :

Owner : ETHOZ Group Ltd  
 SOMPO INSURANCE SINGAPORE PTE. LTD  
 Certificate No : D17MTHCVE000057  
 Vehicle No : GBG-2465-T

Accident Date : 11/09/2021  
 Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)  
 Excess : 0.00      Add Excess : 0.00

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION
	TO APPLY ANTI RUST COATING
	TO SPRAY PAINTING ON AFFECTED AREAS
	<b>Sub Total</b>

REPAIRER AMT (\$)	SURVEYOR APP.
80.00	40. ✓
800.00	700. ✓
<b>3900.00</b>	

8,714.02

Remarks:

*7-10 Days*

**SUB TOTAL**  
 GST 7.0 %      609.98  
**TOTAL**      9,324.00

Surveyor's name:

*Gene A. Ong - 82880282*

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

*21/9/2021*

*P/P  
 before paint photos.*