

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Arthur
date
20/9/21
2/s \$2200
take the other exp.
3 days

VEHICLE No: SMQ 4209X

1PC	REAR BUMPER	deep cut/torn	913.70	\$1,145.20
1PC	REARBUMPER SIDE RETAINER N/S	dent	38.00	\$66.50
1SET	REAR BUMPER CLIPS	new		\$50.00
1PC	REAR BUMPER SPLASH SHIELD N/S	new		\$121.30 X
1SET	REAR BUMPER SPLASH SHIELD CLIPS N/S	new		\$30.00 X
1PC	REAR FENDER N/S	new		\$981.20 X
1PC	REAR FENDER LOWER STICKER N/S	new		\$38.00
1PC	REAR SPORT RIM N/S	waged	680	\$950.00
1PC	REAR SHOCK ABSORBER N/S	new		\$322.00 X
1PC	REAR WHEEL HUB BEARING N/S	Dyed	320.	\$485.00
1PC	REAR AXLE BEAM	new		\$1,655.00 X
				\$5,844.20

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$60.00	X
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$380.00	120
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00	400
TO PUTTY & SPRAY PAINTING	\$900.00	400
TOTAL	\$8,234.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

p. 2039.7
 202
 9,1631.76
 2-1150.00
 2781.76
 202
 2225.