


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMV 690M
at Workshop m/s: 21
of: SKL 72246
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: £ 69k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 4981
Date: _____ Person Contacted: Dep 9h Vehicle: IN / OUT



Veh No: SMV 690M Yr Regn: 14/11/18
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Honda Fit Hybrid c.c. 1496
Colour: Black AC: Insured / Std / NI / NA
Sp. Reading: 71889 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 6P51332948
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/65 R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIQ / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front _____ Rear _____
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 18/9/21 D.O.I. 20/9/21
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rep.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
18/9/21 17:14 31431

27/9/21 1/3 £2800 confirmed with Alan.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$) S + RS SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

um Joseph

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorised
um
20/9/21
2/5 @ 2800
3 days.

VEHICLE No: SMV 690M

1PC	FRONT BUMPER	De/Toon	821.50	\$821.90	/
1PC	FRONT BUMPER SIDE RETAINER N/S	CNE	35.50	\$65.50	/
1SET	FRONT BUMPER CLIPS	um		\$39.00	/
1PC	FRONT BUMPER REINFORCEMENT	um		\$387.80	X
1PC	FRONT BUMPER FOG LAMP N/S	CNE	287.60	\$366.50	/
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	Toon	245.50	\$381.90	/
1PC	HEADLAMP LED N/S	CNE	1550.20	\$1815.20	/
1PC	HEADLAMP LOWER BRACKET N/S	CNE	48.20	\$66.80	/
1PC	FRONT FENDER N/S	R		\$455.20	X
1PC	FRONT FENDER 'HYBRID' EMBLEM N/S	um		\$98.50	/
1PC	FRONT FENDER INNER SHIELD N/S	Toon		\$166.20	/
1SET	FRONT FENDER INNER SHIELD CLIPS N/S	um		\$39.00	/
1PC	FRONT FENDER INNER ARCH PANEL N/S	R		\$291.30	X
				\$4,994.80	

(202)

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	11	\$50.00 X
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM		\$120.00 50
TO CONDUCT WHEEL ALIGNMENT	11	\$120.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$600.00 300
TO PUTTY & SPRAY PAINTING		\$800.00 500
TOTAL		\$6,734.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-3331-80
202
2-2665-44
2-870
3536-44
202
2828.