

OD / YP3004P / CHINA TAIPING

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Fri 1/10/2021 9:36 AM

To: Ding Ding Auto <ding@dingauto.sg>

Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; SUR <sur@lkkauto.com>

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **YP 3004P (Excess \$550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

Rear canopy is insured while sticker is not under coverage.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)