

1 of 2 ? 100% ▼	Find Next
--	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS3/AIG21009793/Gtf3		
78 SHENTON WAY #09-16		Date: 20/09/2021		
AIG BUILDING				
SINGAPORE 079120		Code: AIG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLD 164Y	Veh. Inspected	SJH 9174L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	DIVYASHNI SUBRAMANIAM	Assign Date	20/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/09/2021	Inspection Date	20/09/2021	
Survey held at	160 SIN MING DRIVE #06-10			
Repairer	LIAN HENG PAINTER CO.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				