

JOHN AUTO SERVICES

(53315321B)

BLK, E5, 395A WOODLANDS ROAD,
YEW TEE INDUSTRIAL ESTATE,
SINGAPORE 677984

JOHN AUTO SERVICES

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

Email: hng Lee motor@yahoo.com.sg

Wong Chong Cheong.

SBB 3838x

Date 21/9/21 NO.

1.	Rear tail gate X Repair	\$ 1298.20	
2.	Rear tail gate Lock X NN	\$ 255.20	
3.	Rear tail gate Garnish Assy "H" / CUT	\$ 850.30	282.7
4.	Rear LH tail gate Camp Assy / CUT	\$ 358.10	✓
5.	Rear LH tail gate Camp Assy / CUT	\$ 332.30	✓
6.	Rear RH tail gate Camp Assy X NN	\$ 358.10	
7.	Rear RH tail gate Camp Assy X NN	\$ 332.30	
8.	Rear "CIVIC" emblem / NEC	\$ 38.64	✓
9.	Rear "TYPE R" emblem / NEC	\$ 88.70	53
10.	Rear Boot rubber. / CUT	\$ 188.30	150.8
11.	Rear end Panel X Repair	\$ 551.10	
12.	Rear end panel Garnish / Re	\$ 166.30	122.8
13.	Rear bumper X Repair	\$ 1198.20	
14.	Rear bumper Beam / BT C photos. dot and new	\$ 255.60	✓
15.	Rear 1 Set bumper Clip / NEC	\$ 60.00	SN - 30
16.	Rear bumper Lower. / CRA	\$ 886.40	388
17.	Rear 1st windscreen rubber X NN	\$ 253.40	
18.	Rear windscreen Sealant X NN	\$ 60.00	SN -
19.	Rear no plate / CUT	\$ 45.00	SN 40
20.	Rear Boot Trim Board Clip / NEC	\$ 60.00	SN 20
21.	Rear tail gate Lower Garnish / CRA	\$ 502.30	422
22.	Rear tail gate Lower Garnish Black Cover / CUT	\$ 412.30	276
JOHN AUTO SERVICES (53315321B) Blk 7, 397-D Woodlands Road Yew Tee Industrial Estate Singapore 677996 HP: 85081258			2679.94
			-20%: 2143.95

[Signature]

JOHN AUTO SERVICES
(533153218)
Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

BLK 7, 397-D WOODLANDS ROAD,
YEW TEE INDUSTRIAL ESTATE,
SINGAPORE 677984

Email: *king lee motor@yahoo.com.sg*

STA
wong cheng cheng

CB8 3838x

Date: *21/9/21* NO.

	Labour Charge		
1.	warning fee	\$ 40.00	30
2.	Anti Rust	\$ 60.00	X NN
3.	To spray painting	\$ 1000.00	800
4.	To Remove & Refit Rear spoiler	\$ 80.00	20
5.	To Remove & Refit Rear Wind Screen	\$ 120.00	X NN
6.	To Repair Rear Accident Damage area.	\$ 1000.00	700
7.	To Rear Exhaust Repair	\$ 120.00	X NN
		10,970.74	

X 5 Days

4/5

After repair photo's.

Emo Ref

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHN AUTO SERVICES
(533153218)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

3783.95

-20%: 3000