

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009799/KTCE2**Date:** 19/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00173252101

**Claimant Vehicle No :** FBS2533S **Insured Vehicle No :** SGS1689Z

Date of Loss: 07/09/2021 Nature of Claim: TP Claim No: SNM21D205266/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBS2533S**

Make & Model: HONDA WINNER X, 149cc ABS Engine No: KC34E1127331

Reg. Date: 02/03/2021 (Man. Year: 2020) Chassis No: RLHKC3714LY023786

Colour: Multi-colour Odometer: 22657 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 90/80 R17 Rear Tyre Size: 120/70 R17

Front Left Side: Cheng Shin 4 mm Rear Left Side: Maxxis 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,305.60	900.54	405.06	31.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	460.00	130.00	330.00	71.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,765.60</b>	<b>1,030.54</b>	<b>735.06</b>	<b>41.63</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>1,765.60</b>	<b>800.00</b>	<b>965.60</b>	<b>54.69</b>

**INSPECTION**

Date of Assignment: 20/09/2021

Date Inspected: 21/09/2021 Inspected At: Lim Yew Boo Spray Paint Co (HQ)  
Blk 10 Sin Ming Industrial Estate, #01-10  
Singapore 575645

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Oct 2021)	
<b>Parts:</b>	N/A	HONDA WINNER X 149cc ABS (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBS2533S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	165.00 F	*165.00 FN
2	1		*FRONT FENDER EMBLEM	Necessary	55.60 F	*55.60 FN
3	2		*FRONT FORK ASSY	Bent	780.00 F	*780.00 FN
4	1		*FRONT FORK BRACKET	Repair	65.00 F	*- FN
5	1		*FRONT TYRE	Serviceable	240.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>1,305.60</b>
					<b>- Nett Item Discount on N Items 0.00/10.00% (S\$)</b>	<b>100.06</b>
					<b>Total Parts (S\$)</b>	<b>900.54</b>

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGE	New	60.00	30.00
2	TO DISMANTLE, CHECK, REFIX & LABOUR TO REPLACE ABOVE PARTS	New	400.00	100.00
<b>Gross Labour Cost (\$)</b>			<b>460.00</b>	<b>130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >